



**ENTEGRA**  
COACH®

# RECALL CAMPAIGN

**NHTSA#** 17V-187  
**TC#** 2017-178

**Date of Publication** April 2017

The Spartan motor home chassis equipped with an independent front suspension are being recalled. Reyco Granning, the supplier of the independent front suspension, has indicated that the ball joints may be loose. Spartan Service Centers will perform the Recall Remedy at no charge. To locate the nearest Spartan Service Center Please call 1-800-543-4277 opt 0.

**AFFECTED UNITS**

**2012 Anthem** C14N8059-8068 C14T8055-8056, 8058, 8059  
**2012 Cornerstone** C16D8058-8059 C16F8059

**2013 Aspire** D13H8052-8056, 8058, 8060, 8063-8065, 8067-8069, 8079-8080, 8086  
D13N8060,8062-8066, 8073-8082, 8084-8087, 8089, 8101  
D13T8082, 8055-8058

**2013 Anthem** D14D8051-8098  
D14H8051-8076  
D14N8051-8077, 8079-8148  
D14T8051-8054, 8057-8078  
D14X8052,8054-8065

**2013 Cornerstone** D16J8053-8079  
D16K8053-8105

**2014 Cornerstone** E16B8051-8067  
E16J8051-8072  
E16K8051-8094

**2015 Anthem** F14B8051-8162  
F14D8051-8086  
F14F8051-8055  
F14H8051-8087  
F14L8051-8062  
F14N8051-8097  
F14T8051-8059  
F14X8051-8077

**2015 Cornerstone** F16B8051-8132  
F16J8051-8069  
F16K8051-8104

**2016 Anthem** G14A8051-8058  
G14B8051-8189  
G14D8052-8074  
G14H8051-8075  
G14L8051-8062  
G14N8051-8109

**Affected Units continued 17V-187 2017-178**

**2016 Cornerstone** G16A8051-8076  
G16B8051-8141  
G16J8051-8056  
G16K8051-8080

**2017 Anthem** H14A8051-8073  
H14B8051-8185  
H14D8051-8062  
H14H8051-8081  
H14N8051-8079

**2017 Aspire** H13B8052-8149  
H13H8051-8077  
H13M8051-8059  
H13N8051-8075  
H13P8051-8056  
H13R8051-8089  
H13U8051-8059  
H13W8051-8060

**2017 Cornerstone** H16A8051-8065  
H16B8051-8140  
H16J8051-8054  
H16K8051-8075  
H16W8051-8065  
H16X8051 H16Y8051

**2014 Anthem** E14B8051-8086, 8088-8106  
E14D8051-8108  
E14H8051-8108  
E14N8051-8124  
E14T8051-8067  
E14X8051-8075