



WARRANTY BULLETIN SAFETY CAMPAIGN

CAN-AM® ROADSTER

⚠ WARNING: All involved customers must be notified, all involved units must be corrected as per instruction herein.

Campaign no.: 2017-0002
2017-0003

May 17, 2017

Subject: ▶ **Non-Compliance: Headlights Replacement -- Headlights may Shine Too High** ◀

No. **2017-2**
REVISION 1
May 31st 2017

▶ TEXT(S) BETWEEN ARROWS IS (ARE) MODIFIED ELEMENT(S) TO THE PREVIOUS PUBLICATION. ◀

MODEL YEAR	MODEL	SERIAL NUMBERS
2017	RT™ Series	Refer to campaign monitoring

IMPORTANT

- When a vehicle comes in for service, always type the VIN in Knowledge Center to check for pending campaigns or alerts.
- When performing any work on a vehicle, it is good practice to connect it to BUDS2 to ensure that all needed updates are done.



PROBLEM

▶ The headlights may not meet some photometric requirements of Motor Vehicle Safety Standards in Canada, United States and of UN/ECE, thus could increase the risk of causing a crash. ◀

SOLUTION

Replace headlights.

PARTS REQUIRED

Order through regular channel.

COUNTRY	MODEL	DESCRIPTION	PART NUMBER	QUANTITY
CAN/USA	Base	High/Low beam LH / RH	710001536 / 710001537	1 / 1
	S and LTD		710003098 / 710003097	1 / 1
Europe	S and LTD	High beam LH / RH	710001384 / 710001386	1 / 1
		Low beam LH / RH	710003259 / 710003258	1 / 1

PROCEDURES

Canada and USA Vehicles

To remove the headlights, refer to the *2013 SPYDER SHOP MANUAL*.

Replace headlights.

Adjust headlights. Refer to the *2013 SPYDER SHOP MANUAL*.



rbg2017-002-001_a

HEADLIGHTS TO REPLACE

1. high/low beam


Europe Vehicles

To remove the high beam, refer to the *2013 SPYDER SHOP MANUAL*.

To remove the low beam, refer to the *2014 SPYDER RT SHOP MANUAL SUPPLEMENT*.

Replace headlights.

Adjust headlights. Refer to the *2013 SPYDER SHOP MANUAL*.



rbg2017-002-002_a

HEADLIGHTS TO REPLACE


1. High beam
2. Low beam

WARRANTY

Submit a warranty claim using the following information:

For claiming procedure, refer to the *DEALER/DISTRIBUTOR WARRANTY GUIDE*.

Click in the *REPAIR BOX* while completing your claim on BOSSWeb.



mbg2012-010-004_ben

Canada and USA Vehicles

CAMPAIGN NUMBER	2017-0002
Claim Type	Campaign Claim
Action	Repair
Flat Rate Time	0.7 hour
Expiration Date	-

Europe Vehicles

CAMPAIGN NUMBER	2017-0003
Claim Type	Campaign Claim
Action	Repair
Flat Rate Time	1.5 hour
Expiration Date	-