



Thor Motor Coach Recall Repair Instructions

Recall # 17V-362

Description/Title: **2017 Challenger 37YT Generator Exhaust Pipe**

Affected Product Line(s): **Certain 2017 Challenger 37YT Motorhomes**

Service Campaign # : **RC000138**

Released Date: **8/2/2017**

Failure Code: **Inspect: TMCRC80465Y
Repair: TMCRC80465V**

Document Date: **8/2/2017**

Time Allowed: **Inspect or Adjust: 0.2
Install exhaust pipe: 1.2**

Document Revision: **A**

Issue: On certain 2017 Challenger 37YT motorhomes the generator exhaust pipe may be improperly located or missing.

INSTRUCTIONS:

INSPECT ONLY

Verify the generator exhaust pipe is present and conforms to the standards shown in figure 1. If so, no further action is required.

INSPECT AND ADJUST

If the generator exhaust pipe is present, but not properly located, loosen the exhaust pipe hanger(s) and adjust the position of the exhaust pipe for proper clearance as illustrated in Figure 1.

INSPECT AND INSTALL

If the generator exhaust pipe is not present, please contact Thor Motor Coach Customer Service Dept. at 877-500-1020 for further instructions and the necessary parts.




Figure 1