

SAFETY ADVISORY # 17-302

Cruiser/Volante CO Detector

Keystone is conducting a voluntary **RECALL** notification campaign in accordance with the National Highway Transportation and Safety Act. It has been decided that the vehicles in the recall population were manufactured with Propane detectors instead of a combined Propane/CO detector. Without a properly operated and functioning combined Propane/CO detector, the RV user(s) may not be alerted to the release of carbon monoxide in the RV from any source of combustion.

Models Included: 2018 Cruiser Fifth Wheels

2018 Volante Travel Trailer and Fifth Wheels

Serial Number Ranges: Cruiser J6320297 - J6320352

Volante J6360424 - J6360691

Parts Required: KRV# 422608- Alarm CO - w/Non Digital Display - New Ceiling Mount - w/Battery

Tools Required: - #2 Phillips Screw driver

REPAIR INSTRUCTIONS



Fig. 1

Step 1

Following the installation instructions that come with the carbon monoxide detector, locate a mounting location in the bedroom area and mount the detector, Figure 1. **After the CO detector is installed, please test it immediately to make certain it is functioning properly.**

WARRANTY REIMBURSEMENT

Submit the claim on Key Express using **Flat Rate Code # 7130242K** with **Safety Advisory # 17-302** noted in the customer complaint section of the form. The amount of time authorized for this repair is .3 hours.

If you have any questions, please call Keystone RV Customer Service at **(844) 361-8455**