



AUTOMOBILE DIVISION

American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

SAFETY RECALL NOTICE

VEHICLE IDENTIFICATION NUMBER **9999999999999999**

PLEASE DELIVER TO REGISTERED OWNER

KF0



0000001 00 IV 0.000 0728 99999 -C02-P00001-11 6



JOHN Q SAMPLE
123 ANY STREET
ANYTOWN US 99999

▼ PLEASE DETACH, SIGN BELOW AND PLACE IN RETURN ENVELOPE ▼

INFORMATION CHANGE CARD

PLEASE PROVIDE NAME AND ADDRESS CORRECTIONS ON THE REVERSE SIDE

9999999999999999

◀ VEHICLE IDENTIFICATION NUMBER **KF0**

JOHN Q SAMPLE
123 ANY STREET
ANYTOWN US 99999



PLEASE SIGN AND RETURN THIS CARD ONLY IF YOU HAVE MADE CHANGES

- I no longer own the vehicle. It was:
- Sold (*print name and address of new owner on reverse, if known*)
 - Exported
 - Destroyed
 - Stolen
 - Lease expired, vehicle returned.
 - Other: _____

Nota:
Si usted necesita esta información en español por favor comuníquese con el Centro de Apoyo al Cliente y Campañas de American Honda al 1-888-234-2138.

Signature: **X** _____ Date: _____

SIGNATURE OF REGISTERED OWNER OR LESSEE REQUIRED



0728-02-00-0000001-0001-00000004



AUGUST 2018

RE: 2003 ACCORD
NHTSA Recall 17V-220

URGENT!

- Your vehicle is included in an urgent safety recall and you should have the recall repair done immediately.
 - Any authorized Honda dealer will perform the recall repair **FOR FREE**.
-
- If you have any questions about this notice, or you need assistance locating a dealer, contact American Honda's Customer Support & Campaign Center at 1-888-234-2138. You may also visit www.recalls.honda.com to use Ask Dave, our 24/7 virtual agent.

Dear JOHN SAMPLE:

What is the reason for this notice?

Our records indicate that an **URGENT SAFETY RECALL** has not been completed on this vehicle; refer to the address card for the affected VIN (Vehicle Identification Number). The original factory-installed passenger frontal airbag module was replaced with a Honda service part that utilized a Takata airbag inflator. In the event that a vehicle with replacement airbag module is involved in a crash requiring deployment of the passenger front airbag, the airbag inflator may rupture, causing metal fragments to pass through the airbag cushion material, potentially resulting in injury to vehicle occupants. The risk of such an occurrence increases over time. It is imperative you schedule an appointment with an authorized Honda dealer **IMMEDIATELY**.

What will Honda do?

Call any authorized Honda dealer and have your vehicle inspected to see if a replacement airbag module with a Takata airbag inflator was installed and, if one was, replace the passenger frontal airbag inflator **FOR FREE**. A free rental car will be available to the vehicle owner for the day of the recall repair or longer if a replacement part is temporarily unavailable.

We apologize for any inconvenience this safety recall may cause you.

Sincerely,

American Honda Motor Co., Inc.



NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #17-024

KF0

0728-02-00-00000001-0002-00000003