

IMPORTANT SAFETY RECALL

This is a follow up notification regarding NHTSA recall 17V-426 (Triumph SB 549) for your Motorcycle with the following VIN: xxxxxxxxxxxxxxxxx.

As of January 8th 2018, our records indicate that the recall remedy for this motorcycle has not been completed. Using your 17 digit VIN, you can go to www.Triumphmotorcycles.com/safety-recall-search to check for open recalls and to locate your closest Triumph dealer for scheduling the recall remedy.

The details concerning this recall, which may also be found in the original recall notification letter we mailed to you, are as follows:

The reason for this recall notice: Your motorcycle is supplied with hazard warning light functionality. When engaged, both the left hand and right hand front and rear indicators will illuminate and flash in unison. The hazard light electrical wiring from the right hand handlebar switch cube is connected to your motorcycle's main harness via an electrical block connector located within the head lamp bowl. On some motorcycles there is insufficient free length in the wiring to accommodate the full steering movement. Where there is insufficient free length, the wires will be stretched and may become damaged. Once damaged, hazard warning light functionality is compromised and they may not operate. These circumstances will not affect your individual indicator operation. Your left hand and right hand indicators will continue to work normally. Loss of hazard warning light functionality presents an increased risk to your safety.

What Triumph Motorcycles Ltd & your dealer will do: Triumph Motorcycles Ltd has authorized your dealer to fit a new electrical block connector and additional length of wiring that will provide acceptable free length. This repair will be performed free of charge to you, including parts and labour. This repair should take less than 45 minutes. However, it may be necessary to make your motorcycle available for a longer period of time.

What you must do to ensure your safety: Please make an appointment with your authorized Triumph motorcycles dealer to have this important remedy performed on your motorcycle as soon as possible.

Federal regulations require that any vehicle lessor receiving this recall notice forward a copy of this notice to the lessee within 10 days.

If you need help: Please contact your authorized Triumph dealer should you have any questions or encounter any difficulty regarding this recall. In the event your dealer is unable to remedy your motorcycle, please contact Triumph Motorcycles America on 1-678-854-2010.

If an authorized Triumph dealer or Triumph Motorcycle America Ltd fails or is unable to perform this remedy without charge within a reasonable amount of time, you may contact the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE., Washington, D.C., 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own the motorcycle listed above, please contact Triumph at 1-678-854-2010 and provide any information you can furnish that will assist us in locating the new owner.

We apologise for any inconvenience this may cause you. However, we have taken this action in the best interest of your safety and your continued satisfaction with your Triumph motorcycle. We appreciate your attention and cooperation in this important matter.

Sincerely

Triumph Motorcycles America Ltd.