



Ford Motor Company
Ford Customer Service Division
P.O. Box 1904
Dearborn, Michigan 48121-1904

57 / 01 / 000011695 / 0051



June 2019

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2017 Motorhome Chassis has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

KEY INFORMATION

- Your vehicle is involved in an important safety recall
- Your safety is important to us. Schedule an appointment to have service procedure completed
- This procedure will be performed free of charge

Recall Number 17S41 - Channel Hydraulic Brakes - Missing Ball Plugs
and Description:

What is the Issue?

On your vehicle, the Hydraulic Electronic Control Unit (HECU) in the braking system may have been built without ball plugs in the hydraulic block.

This could result in air ingestion or brake fluid leaking during an Electronic Brake Distribution (EBD) or Anti-lock Brake System (ABS) activation. These conditions may increase the risk of a crash.

- Air ingestion may result in unexpected, increased brake pedal travel.
- The amount of brake fluid that leaks is dependent on the number and duration of EBD and ABS events that occur. Sufficient loss of brake fluid may result in increased pedal travel and/or increased stopping distance. The brake warning light may illuminate as a result.

What Are We Asking You To Do?

Please contact your dealer to schedule an appointment to have this important service procedure completed. If you do not already have a servicing dealer, you can access www.Fordowner.com for dealer addresses, maps and driving instructions.

The vehicle owner is responsible for having this service action performed. Ford Motor Company reserves the right to deny coverage for any vehicle damage that may result from failure to have this recall performed on a timely basis. Therefore, please have this recall performed as soon as possible.

Service Assistance: If you have additional questions, please contact the Ford Motor Company Customer Relationship Center at 1-866-436-7332 and one of our representatives will be happy to assist you. For the hearing impaired call 1-800-232-5952 (TDD). Office Hours are Monday through Friday: 8:00AM - 5:00PM (Your Local Time).

If you wish to contact us through the Internet, our address is: www.Fordowner.com.

If your authorized dealer has recently completed this recall repair, please disregard this reminder.

We apologize for any inconvenience this may cause and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

Thank you for your attention to this important matter.

Ford Customer Service Division



Ford Motor Company
División de Servicio al Cliente de Ford
P. O. Box 1904
Dearborn, Michigan 48121

59 / 01 / 000011695 / 0051



Junio de 2019

* * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * *

SegUR nuestros registros, no se realizaron en sur 2017 Motorhome Chassis las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

INFORMACIÓN CLAVE

- Su vehículo ha sido incluido en una importante campaña de seguridad.
- Su seguridad es muy importante para nosotros. Programe una cita para completar el procedimiento de servicio.
- Este procedimiento se llevará a cabo sin costo alguno.
- *Si necesita ayuda o tiene alguna pregunta, por favor llame al Centro de Relación con Clientes al 1-866-436-7332 y presione 2 para Español*

Número y
descripción de
la campaña:

17S41 - Frenos hidráulicos de canales 17S41 - Tapón de bola faltante

¿Cuál es el
problema?

En su vehículo, la unidad electrónica de control hidráulico (HECU) en el sistema de frenado podría haber sido fabricada sin los tapones de bola en el bloque hidráulico.

Esto podría traducirse en una entrada de aire o una fuga de líquido de frenos durante la distribución del freno electrónico (EBD) o una activación del sistema de frenos antibloqueo (ABS). Estas condiciones podrían aumentar el riesgo de choque.

- Una entrada de aire podría producir un recorrido inesperado y aumentado del pedal del freno.
- La cantidad de líquido de frenos que fuga depende de la cantidad y la duración de los eventos de EBD y ABS que ocurran. Una pérdida suficiente de líquido de frenos podría ocasionar un recorrido aumentado del pedal y/o una mayor distancia de detención. Es probable que como resultado de esto se encienda la luz de advertencia de frenos.

¿Que le
solicitamos
hacer?

Comuníquese con su distribuidor para programar una cita para completar este importante procedimiento de servicio. Si aún no tiene un distribuidor para realizar el servicio, puede acceder a www.Fordowner.com para conocer las direcciones de los distribuidores, ver mapas y obtener las instrucciones para llegar.

El propietario del vehhvehh es responsable de realizar estas acciones de servicio. Ford Motor Company se reserva el derecho de negar la cobertura en caso de que el vehículo hubiese sufrido daños por no haber realizado la campaña de manera oportuna. Por lo tanto, le solicitamos que realice esta campaña lo antes posible.

Servicio de asistencia:

Si tiene mme preguntas, comununas, con el Centro de Relacio con Clientes de Ford Motor Company al 1-866-436-7332 y uno de nuestros representantes con gusto lo atenderá. Las personas con problemas de audición pueden llamar al 1-800-232-5952 (TDD). El horario de atención es de lunes a viernes, de 8:00 a. m. a 5:00 p. m. (hora local).

Si desea comunicarse con nosotros a travra de Internet, nuestra direcciid es:
www.Fordowner.com.

Si ya realizz esta reparaciir de seguridad en su distribuidor autorizado, ignore este recordatorio.

Lamentamos cualquier inconveniente causado y deseamos asegurarle que, con su ayuda, corregiremos el problema. Nuestro compromiso, junto con el de su distribuidor, es ofrecerle servicio y apoyo de alto nivel.

Gracias por su atenciic en este asunto sumamente importante.

Divisiyo de Servicio al Cliente de Ford