



Date: May 03, 2017

GEM

Bulletin Number: L-17-01

Model Years: 2016-2017

Safety Bulletin

Service Bulletin

Service Alert Fax

Distribution: Owner/Principal Service Manager Sales Manager Parts Manager Technicians

This Service Bulletin is located at www.polarisdealers.com

-Confidential and Proprietary-

**IMPORTANT STOP SALE SAFETY NOTICE!
STOP SELLING ALL STEEL WHEEL GEM VEHICLES IMMEDIATELY.**

SUBJECT: 2016-2017 GEM STEEL WHEEL LUG NUT TORQUE STOP SALE

PURPOSE:

Polaris is issuing a STOP SALE on all 2016-2017 GEM Models with steel wheels to address the following concern:

On some models equipped with steel wheels, the wheel lugs may become loose over time, which may allow the wheel to separate from the vehicle and pose a safety hazard. Vehicles with aluminum wheels are not affected by this concern.



AFFECTED



NOT AFFECTED

Polaris is currently evaluating a comprehensive repair for this concern. Polaris will provide an update on the status of the repair procedure no later than Friday June 2, 2017. At the time of availability, Polaris will re-issue this communication with additional parts and repair information. Until then, any updates regarding Safety Bulletin L-17-01 will be posted in the STOP Site Special Alerts.

CONSUMER NOTIFICATION:

When repair details are available, Polaris will notify consumers by mail immediately and follow-up with additional repair plans. At that point, dealers should also contact owners of affected VINs to inform them of the announcement.

AFFECTED MODELS:

Model Year	Models	Vehicle Identification Number Range
2016-2017	e2	Reference "Unit Inquiry" on the dealer website or the Service Bulletin list on the STOP site to lookup affected units.
	e4	
	e6	
	eL XD	