

From:
Sent:
To:
Subject:

[View online](#)

A large, red, reflective warning triangle is positioned on the right side of the banner. It has a white exclamation mark in the center. The background of the banner is a dark blue gradient.

**Schedule service
for your Sonata's
Recall today.**

Your safety is our priority.

Schedule appointment

**A Recall has been issued on
your Sonata's Engine.**

This notice applies to your vehicle, VIN ending in: 030606.

What is the problem?

Excess metal debris may have been generated from factory machining operations. The debris can be forced into the connecting rod oiling passages, restricting oil flow to the connecting rod bearings and increasing the potential of premature bearing wear. The condition would cause the vehicle to stall while in motion, **increasing the risk of a crash.**

What will Hyundai do?

Your Hyundai dealer will inspect your vehicle for indications of a worn connecting rod bearing and if necessary, repair your vehicle. This procedure will be performed at **NO CHARGE** to you. **For your safety, schedule an appointment as soon as possible.**

[Schedule appointment](#)



For more information:

If you'd like more information on the details of this important recall including affected vehicles or frequently asked questions, you may view the [official campaign information here.](#)

