

17V-495
Model Year 2012-2013
BMW M6 Coupe, M6 Convertible, X3 SAV
Driver Front Air Bag
In-Car / In-App Communication – Safety Recall Reminder
12 Sep 2023

Title:

BMW Safety Recall 17V-495 Driver's Front Air Bag Module

Text:

In the event of a crash necessitating deployment of the driver's front air bag, the inflator housing could separate from the base plate if it was incorrectly welded. This could result in metal and other debris passing through the air bag cushion material striking the driver or other occupants in the vehicle, potentially resulting in serious injury or death.

Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.

Advise all drivers of this important information.

For the latest updates to this recall, please visit bmwusa.com/recall.

Short Text:

Important Safety Recall 17V-495 Driver's Front Air Bag Module: Contact an authorized BMW center immediately to get your vehicle repaired for FREE. For the latest updates to this recall, please visit bmwusa.com/recall. Dealer locator: bmwusa.com/dealer.

Pop-Up:

Important Safety Recall: Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.