

AMENDED DEFECT INFORMATION REPORT 17V-545
November 9, 2017

REVIEWED BY:
JOHN TURLEY
NOV. 9 - 2017
John Turley

573.6(c)(1)

Name of manufacturer: Honda Motor Co., Ltd.
Honda of America Mfg., Inc.
Honda of Canada Mfg.
Honda Manufacturing of Alabama LLC
Honda Manufacturing of Indiana, LLC
Honda de Mexico, S.A. De C.V.

Manufacturer's agent: John Turley
American Honda Motor Co., Inc.
1919 Torrance Blvd.
Torrance, CA 90501-2746

573.6(c)(2)

Identification of potentially affected vehicles:

<u>Make/Model</u>	<u>Description</u>	<u>VIN Range/Dates of Manufacture</u>
See Attached List		

573.6(c)(2)(iv)

Identification of affected component:

Component: Passenger Airbag Inflator Kit
Part No: 04790-TA0-407; 04790-SNA-407; 04790-SWA-407; 04790-TK6-407;
04790-TM8-407; 04790-SZA-407; 04790-TL2-407
Country of Origin: USA
Manufacturer: T.K. Holdings, Inc.
Contact Name: D. Michael Rains
Address: 111 Peyer Court, Romeo, MI 48065
Telephone No.: (586) 336-5552

Description of the basis for the determination of the recall population:

The recall population was determined based on dealership repair records. The VIN range reflects all possible vehicles that could potentially experience the problem.

Description of how the vehicles being recalled differ from similar vehicles not included in the recall:

This expanded recall is specific to vehicles that had passenger frontal airbag inflator recall repairs completed at dealerships other than the initially involved dealership. During dealership audits, these vehicles were identified as potentially having had the recall repair done incorrectly.

573.6(c)(3)

Total number of potentially affected vehicles: 646
2,611 (expansion)
3,257

573.6(c)(4)

Percentage of affected vehicles that contain the defect: Unknown

573.6(c)(5)

Defect description:

Recall replacement passenger frontal airbag inflators may have been incorrectly installed at certain dealerships. If the vehicle has an incorrectly installed inflator and is involved in a crash, the passenger frontal airbag will not deploy normally, increasing the risk of injury.

573.6(c)(6)

Chronology:

- | | |
|-----------------|--|
| Aug. 7, 2017 | A dealership notified Honda of incorrect installation of recall replacement passenger frontal airbag inflators. |
| Aug. 7-15, 2017 | Honda begins investigation and requested detailed reporting and analysis from the involved dealership. |
| Aug. 28, 2017 | Honda made the determination that a defect related to motor vehicle safety exists and decided to conduct a safety recall. |
| Sept. 2, 2017 | Honda starts meetings at all Honda and Acura dealerships. |
| Sept.-Oct. 2017 | Dealership meetings include: <ul style="list-style-type: none">• Required attendance for all dealer staff, including technicians, involved in SRS repairs.• Reviewing all SRS training materials and passenger frontal airbag inflator repair procedures.• Interviewing of technicians on correct passenger frontal airbag inflator repair procedures and technicians were asked to report any issues.• As confirmation of the interview, vehicles that returned to the dealership for service were audited.• Sign-offs by Honda & Acura District Parts & Service Managers, dealer management, dealer technicians and dealer parts associates as evidence of attending meetings, reviewing training materials and repair procedures. |
| Oct. 26, 2017 | Honda identified suspect vehicles based on dealership audits. |
| Nov. 2, 2017 | Honda made the determination that a defect related to motor vehicle safety exists and decided to conduct a safety recall expansion. |

As of Nov. 2, 2017, Honda has not received any field reports, warranty claims, nor reports of injuries or deaths related to this issue.

573.6(c)(8)(i)

Program for remedying the defect:

Registered owners of all affected vehicles will be contacted by mail and asked to take their vehicle to a Honda automobile dealer. The dealer will replace the passenger frontal airbag module assembly for free.

573.6(c)(8)(ii)

The estimated date to start notification to dealers: Nov. 10, 2017

The estimated date to start notifications to owners: Dec. 9, 2017

573.6(c)(9)

Representative copies of all notices, bulletins and other communications:

A copy of the dealer service bulletin other dealer communication will be submitted to your office as soon as possible.

573.6(c)(10)

Proposed owner notification letter submission:

A draft of the owner notification letter will be submitted to your office as soon as possible.

573.6(c)(11)

Manufacturer's campaign number: O07, Y0A, N06, O09, G05, M04, Y01, Y0F

Identification of potentially affected vehicles

Model	Model Year	VIN Range	Dates of Manufacture
HONDA ACCORD	2008	JHMCP26718C001305 to JHMCP26408C076518	July 20, 2007 to May 13, 2008
		1HGCP26888A001325 to 1HGCP26418A163939	August 15, 2007 to July 21, 2008
		1HGCP368X8A002563 to 1HGCP36838A087780	September 6, 2007 to July 21, 2008
		1HGCS128X8A000546 to 1HGCS12778A030255	September 21, 2007 to July 25, 2008
		1HGCS22838A001169 to 1HGCS22838A016514	October 10, 2007 to June 20, 2008
	2009	JHMCP264X9C000189 to JHMCP26309C017140	June 26, 2008 to March 19, 2009
		5KBCP36859B001197 to 5KBCP36889B502455	July 17, 2009 to August 11, 2009
		1HGCP26729A000101 to 1HGCP26429A197292	July 25, 2008 to August 7, 2009
		1HGCP36829A000825 to 1HGCP36879A049390	July 28, 2008 to July 23, 2009
		1HGCS12799A001440 to 1HGCS12309A024568	August 7, 2008 to July 23, 2009
		1HGCS22889A000262 to 1HGCS22829A011886	July 29, 2008 to July 29, 2009
	2010	5KBCP3F89AB002146 to 5KBCP3F84AB011756	August 26, 2009 to December 23, 2009
		1HGCP2F74AA001416 to 1HGCP2F79AA195280	August 17, 2009 to August 10, 2010
		1HGCP3F81AA003106 to 1HGCP3F87AA031699	October 7, 2009 to July 29, 2010
		1HGCS1B83AA000958 to 1HGCS1B33AA017831	August 26, 2009 to May 28, 2010
		1HGCS2B88AA000637 to 1HGCS2B87AA009068	August 24, 2009 to April 30, 2010
	2011	5KBCP3F8XBB001833 to 5KBCP3F88BB004598	September 16, 2010 to December 21, 2010
		1HGCP2F85BA001239 to 1HGCP2F85BA157961	August 17, 2010 to August 12, 2011
		1HGCP3F88BA002181 to 1HGCP3F80BA018598	August 27, 2010 to February 7, 2011
		1HGCS1B32BA002495 to 1HGCS1B88BA017224	September 16, 2010 to August 2, 2011
1HGCS2B86BA001920 to 1HGCS2B89BA008411		September 15, 2010 to June 23, 2011	
2012	1HGCP2F65CA001774 to 1HGCP2F35CA243745	August 18, 2011 to August 23, 2012	
	1HGCP3F86CA000060 to 1HGCP3F81CA042328	August 22, 2011 to August 17, 2012	
	1HGCS1B84CA000535 to 1HGCS1B36CA023268	August 18, 2011 to August 21, 2012	
	1HGCS2B89CA003193 to 1HGCS2B81CA010851	December 19, 2011 to June 27, 2012	
HONDA ACCORD CROSSTOUR	2010	5J6TF1H56AL000242 to 5J6TF1H59AL016497	November 3, 2009 to September 7, 2010
		5J6TF2H54AL006692 to 5J6TF2H5XAL011217	February 25, 2010 to May 8, 2010
	2011	5J6TF1H53BL000720 to 5J6TF1H5XBL002299	November 4, 2010 to March 4, 2011
2012	5J6TF2H50BL006254	May 12, 2011	
HONDA CIVIC	2006	1HGFA16896L000968 to 1HGFA16566L152843	August 31, 2005 to August 30, 2006
		2HGFA16816H500037 to 2HGFA16566H526557	September 28, 2005 to August 3, 2006
		2HGFG12826H501461 to 2HGFG12816H584266	September 9, 2005 to September 1, 2006
		JHMFA15586S001099 to JHMFA16526S011934	July 19, 2005 to June 22, 2006
		JHMFA362X6S001296 to JHMFA36256S027014	October 4, 2005 to July 31, 2006
		1HGFA16837L000725 to 1HGFA16837L142900	September 5, 2006 to August 14, 2007
	2007	1HGFA46537L000005 to 1HGFA46567L000368	September 26, 2006 to January 24, 2007
		2HGFA16587H301011 to 2HGFA16527H512169	February 15, 2007 to August 24, 2007
		2HGFA55597H704200 to 2HGFA55587H715169	December 20, 2006 to July 25, 2007
		2HGFG12867H501707 to 2HGFG11877H581844	September 7, 2006 to August 1, 2007
		2HGFG21527H700671 to 2HGFG21577H711326	September 26, 2006 to August 2, 2007
		JHMFA168X7S000157 to JHMFA16527S007366	September 23, 2006 to December 23, 2006
		JHMFA36237S000668 to JHMFA362X7S031707	September 15, 2006 to August 9, 2007
		1HGFA16818L000367 to 1HGFA16948L118471	August 20, 2007 to August 16, 2008
	2008	2HGFA165X8H302565 to 2HGFA16838H536623	September 4, 2007 to August 25, 2008
		2HGFA55528H700992 to 2HGFA55528H708493	October 10, 2007 to May 14, 2008
		2HGFG11628H504346 to 2HGFG12628H581118	September 5, 2007 to August 21, 2008
		2HGFG21548H705873 to 2HGFG21538H706755	April 1, 2008 to May 6, 2008
		JHMFA36228S000789 to JHMFA36278S027602	September 17, 2007 to June 26, 2008
		19XFA16529E000361 to 19XFA16589E052304	November 27, 2008 to September 3, 2009
	2009	1HGFA16949L000129 to 1HGFA16599L028649	August 21, 2008 to February 11, 2009
		1HGFA46549L001019	November 21, 2008
		2HGFA16559H300031 to 2HGFA16839H548210	August 26, 2008 to August 26, 2009
		2HGFA55569H702312 to 2HGFA55509H707439	October 28, 2008 to April 8, 2009
2HGFG12669H500445 to 2HGFG12639H539929		August 28, 2008 to May 19, 2009	
2HGFG21589H700788 to 2HGFG21589H704436		September 30, 2008 to March 11, 2009	
JHMFA36289S000443 to JHMFA36219S018024		August 6, 2008 to January 22, 2009	

Identification of potentially affected vehicles

Model	Model Year	VIN Range	Dates of Manufacture	
HONDA CIVIC	2010	19XFA1F53AE016234 to 19XFA1F52AE085741	November 5, 2009 to August 17, 2010	
		2HGFA1F5XAH301647 to 2HGFA1F54AH588581	August 31, 2009 to August 25, 2010	
		2HGFG1A69AH503474 to 2HGFG1B67AH536536	October 16, 2009 to August 6, 2010	
		JHMFA3F2XAS005731	April 7, 2010	
	2011	19XFA1F69BE009475 to 19XFA1F50BE046874	October 5, 2010 to March 16, 2011	
		19XFA4F5XBE000292 to 19XFA4F52BE000402	January 4, 2011 to January 13, 2011	
		2HGFA1F86BH500223 to 2HGFA1F55BH548852	August 26, 2010 to March 3, 2011	
		2HGFG1B89BH503069 to 2HGFG1B6XBH519344	September 21, 2010 to March 4, 2011	
		JHMFA3F20BS001186	October 26, 2010	
HONDA CR-V	2007	JHLRE38567C000638 to JHLRE38767C083361	August 2, 2006 to August 21, 2007	
		JHLRE48347C000089 to JHLRE48747C124060	July 20, 2006 to August 21, 2007	
		5J6RE38367L000340 to 5J6RE38377L002078	May 8, 2007 to September 21, 2007	
		5J6RE48737L000241 to 5J6RE48777L017902	March 9, 2007 to September 14, 2007	
	2008	JHLRE38548C000140 to JHLRE38358C056618	August 22, 2007 to July 17, 2008	
		JHLRE48588C001135 to JHLRE48578C081818	August 25, 2007 to July 29, 2008	
		5J6RE38328L000370 to 5J6RE38358L009970	January 2, 2008 to September 12, 2008	
		5J6RE48548L002032 to 5J6RE48708L051360	November 28, 2007 to September 22, 2008	
		3CZRE38398G700089 to 3CZRE38378G707896	November 27, 2007 to June 23, 2008	
		3CZRE485X8G700061 to 3CZRE48568G703586	November 10, 2007 to September 29, 2008	
	2009	JHLRE38789C000015 to JHLRE38719C014368	August 18, 2008 to June 19, 2009	
		JHLRE48509C000806 to JHLRE48369C024672	August 21, 2008 to July 30, 2009	
		5J6RE38729L001247 to 5J6RE38389L032936	October 3, 2008 to August 25, 2009	
		5J6RE48719L001987 to 5J6RE48369L070199	September 26, 2008 to September 11, 2009	
		3CZRE38559G700108 to 3CZRE38399G709361	October 24, 2008 to September 29, 2009	
		3CZRE48509G700104 to 3CZRE48519G708261	October 16, 2008 to September 12, 2009	
	2010	JHLRE3H76AC002334 to JHLRE3H3XAC009302	April 19, 2010 to July 9, 2010	
		JHLRE4H71AC006457 to JHLRE4H76AC015655	May 18, 2010 to July 29, 2010	
		5J6RE3H59AL001510 to 5J6RE3H74AL050812	September 18, 2009 to September 7, 2010	
		5J6RE4H37AL003342 to 5J6RE4H57AL091441	September 24, 2009 to August 10, 2010	
		3CZRE3H5XAG700383 to 3CZRE3H31AG706023	November 27, 2009 to October 1, 2010	
		3CZRE4H58AG704762	May 5, 2010	
	2011	JHLRE3H79BC002393 to JHLRE3H42BC014746	September 1, 2010 to September 11, 2011	
		JHLRE4H42BC002554 to JHLRE4H76BC035020	August 27, 2010 to September 19, 2011	
		5J6RE3H41BL001302 to 5J6RE3H35BL060876	September 17, 2010 to November 17, 2011	
		5J6RE4H76BL002882 to 5J6RE4H42BL123401	September 23, 2010 to November 17, 2011	
		3CZRE3H52BG700573 to 3CZRE3H35BG705488	January 25, 2011 to November 17, 2011	
	HONDA FIT	2009	JHMGE88219C000331 to JHMGE88429C004471	May 12, 2009 to July 1, 2009
			JHMGE87499S000201 to JHMGE88459S074052	July 18, 2008 to April 28, 2009
		2010	JHMGE8H48AC010120 to JHMGE8H43AC039086	October 30, 2009 to October 22, 2010
JHMGE8H20AS010505 to JHMGE8G42AS016728			June 8, 2010 to July 8, 2010	
2011		JHMGE8H50BC001647 to JHMGE8H32BC028833	November 10, 2010 to July 31, 2011	
		JHMGE8H56CC008717 to JHMGE8H54CC040209	October 20, 2011 to June 22, 2012	
		JHMGE8G5XCS001793 to JHMGE8H39CS006433	October 22, 2011 to December 14, 2011	
HONDA INSIGHT	2010	JHMZE2H76AS003186 to JHMZE2H55AS038980	February 20, 2009 to May 13, 2010	
	2011	JHMZE2H78BS002140 to JHMZE2H5XBS010710	November 11, 2010 to May 23, 2011	
	2012	JHMZE2H77CS000588 to JHMZE2H58CS003594	September 21, 2011 to December 20, 2011	
HONDA PILOT	2009	5FNYP38489B001258 to 5FNYP38929B026183	May 7, 2008 to January 15, 2009	
		5FNYP48559B001149 to 5FNYP48289B055566	April 16, 2008 to March 30, 2009	
	2010	5FNYP3H59AB011469 to 5FNYP3H67AB020793	October 16, 2009 to January 29, 2010	
		5FNYP4H94AB008732 to 5FNYP4H22AB025869	June 26, 2009 to November 18, 2009	
	2011	5FNYP3H47BB001189 to 5FNYP3H5XBB058575	February 24, 2010 to August 29, 2011	
		5FNYP4H63BB013136 to 5FNYP4H2XBB103168	April 23, 2010 to August 11, 2011	
	2012	5FNYP3H26CB002513 to 5FNYP3H98CB040578	September 12, 2011 to August 9, 2012	
		5FNYP4H23CB005990 to 5FNYP4H92CB084758	September 19, 2011 to August 27, 2012	

573.6(c)(2)

Identification of potentially affected vehicles

Model	Model Year	VIN Range	Dates of Manufacture
ACURA TSX	2009	JH4CU26689C002081 to JH4CU26679C037288	March 13, 2008 to December 19, 2008
	2010	JH4CU2F6XAC002913 to JH4CU2F61AC042426	June 11, 2009 to October 4, 2010
	2011	JH4CU2F65BC008037	February 4, 2011
		JH4CW2H61BC000203 to JH4CW2H5XBC001700	November 10, 2010 to February 8, 2011
	2012	JH4CU2F66CC003270 to JH4CU2E81CC030508	September 21, 2011 to August 9, 2012
		JH4CW2H64CC002920 to JH4CW2H65CC005339	March 2, 2012 to June 8, 2012