

From:
Sent:
To:
Subject:

[View online](#)

A large, red, reflective warning triangle with a white exclamation mark in the center, set against a blurred background of a road and trees.

**Schedule service
for your Sonata's
Recall today.**

Your safety is our priority.

Schedule appointment

**A Recall has been issued for your Sonata's
Seat Belt Anchor.**

This notice applies to your vehicle, VIN ending in: 725717

What is the problem?

The front seat belts in your Sonata incorporate a seat belt anchor pretensioner fastened to the vehicle's inner sill structure. If the connector does not fully latch when the linkage is pressed onto the connector, the seat belt can detach from the anchor pretensioner. If the seat belt linkage detaches from the anchor pretensioner in a collision, **the risk of injury to the occupant is increased.**

What will Hyundai do?

In March of 2017 Hyundai notified you that a Hyundai dealer will verify the connection between the seat belt linkage and the anchor pretensioner's cable connector for both front seat belts. In addition to verifying the connection, a Hyundai dealer will attach a warning label to the anchor pretensioner latch housings on both front seat belts. This procedure will be performed in your dealer's service drive in less than 15 minutes at **NO CHARGE** to you. **For your safety, schedule an appointment as soon as possible.**

[Schedule appointment](#)



For more information:

If you would like more information on the details of this important recall including affected vehicles or frequently asked questions, you may view the [official campaign information here](#).