

NEW SAFETY RECALLS – N124 AND H056

INSTRUMENT CLUSTER DISPLAY BLANKS OUT



- 2 new safety recalls and stop sale were announced November 1st- N124 for Land Rover and H056 Jaguar. Announcement Bulletins emailed and published to Infotrail/JBN
- Certain vehicles fitted with full Thin Film Transistor Display (TFT) in the following model ranges may experience an intermittent complete loss of instrument cluster display including speedometer and warnings.
 - 7,036 US and 1,371 Canadian Jaguar XJ 16-17MY, 17-18 MY F-PACE and XF; 18MY XE
 - 23,553 US and 2,628 Canadian 17MY Range Rover/Range Rover Sport
- All affected vehicles identified in DDW and unsold VIN are listed on JBN/Infotrail
- Repair will be new instrument cluster software.
- Repair bulletin expected to be available during w/c Nov 6th
- Initial repair process will be a 2 hour software download.
- Enhanced software delivery process with download <5 mins is expected during December
- Customer mailing on or before December 19th