

May 17, 2018

Ms. Lisa Hancock Corporate Recall Administrator Blue Bird Body Company 402 Blue Bird Blvd Fort Valley, GA 31069

Subject: Throttle Input may not be Blocked as Expected

Dear Ms. Hancock:

This letter serves to acknowledge Blue Bird Body Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: BLUE BIRD/VISION/2017-2018

Mfr's Report Date: April 24, 2018

NHTSA Campaign Number: 18V-259

Components: VEHICLE SPEED CONTROL:ACCELERATOR PEDAL

Potential Number of Units Affected: 364

Problem Description:

Blue Bird Body Company (Blue Bird) is recalling certain 2017-2018 Blue Bird Vision school buses equipped with Gen4 Ford engines with an optional brake and throttle interlock. The brake and throttle interlock is supposed to apply the service brakes and prevent accelerator pedal input when activated, however the throttle input is not being blocked.

Consequence:

If throttle input is allowed, the bus may be able to overpower the applied brake, causing the bus to move unexpectedly, increasing the risk of a crash or an injury.

Remedy:

Blue Bird will notify owners, and dealers will update the Smart Relay Module software. The recall is expected to begin in May 2018. Owners may contact Blue Bird customer service at 1-478-822-2242. Blue Bird's number for this recall is R18ZF - SB.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150MR 18V-259

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigations Enforcement

