



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

November 20, 2018

Mr. Todd Fronckowiak
Assistant Director, Global Automotive Safety Compliance
Ford Motor Company
Fairlane Plaza South, Suite #500
330 Town Center Drive
Dearborn, MI 48126-2738

NEF-150JK
18V-807

Subject: Fuel Pressure Sensor may Leak Fuel

Dear Mr. Fronckowiak:

This letter serves to acknowledge Ford Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FORD/EXPLORER/2018

Mfr's Report Date: November 14, 2018

NHTSA Campaign Number: 18V-807

Components:

FUEL SYSTEM, GASOLINE

Potential Number of Units Affected: 144

Problem Description:

Ford Motor Company (Ford) is recalling certain 2018 Ford Explorer vehicles equipped with 2.3L or 3.5L GTDI engine. Due to an assembly error, the fuel pressure sensor may leak fuel.

Consequence:

A fuel leak in the presence of an ignition source can increase the risk of a fire.

Remedy:

Ford will notify owners, and dealers will replace the fuel line assembly, free of charge. The recall is expected to begin December 3, 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 18S35.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov

We have received Ford's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:


Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian". The signature is fluid and cursive, with a long horizontal stroke at the end.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement