



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

November 30, 2018

Mr. David Partin
Cruiser RV
2831 Dexter Drive
Elkhart, IN 46514

NEF-150MR
18V-820

Subject: Insufficient Grease on Bearings may cause Failure

Dear Mr. Partin:

This letter serves to acknowledge Cruiser RV's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

CRUISER RV/MPG/2019
CRUISER RV/RADIANCE ULTRA LITE/2019

Mfr's Report Date: November 20, 2018

NHTSA Campaign Number: 18V-820

Components:

SUSPENSION:REAR:AXLE:NON-POWERED AXLE ASSEMBLY

Potential Number of Units Affected: 25

Problem Description:

Cruiser RV (Cruiser) is recalling certain 2019 Cruiser MPG and Radiance Ultra Light recreational trailers, built on D28H, D35, D40, or D44 trailer axles. The inner hub bearings may not have been sufficiently greased, which can cause the bearings to overheat and fail.

Consequence:

If the bearings overheat, the hub may fail, affecting handling and increasing the risk of a crash.

Remedy:

Cruiser will notify owners, and dealers will inspect and repair the hubs and bearings, as necessary, free of charge. The recall is expected to begin January 15, 2019. Owners may contact Cruiser customer service at 1-574-206-7920. Cruiser's number for this recall is 99.03.16.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

NHTSA is missing critical, required information for this safety recall. This information must be supplied through the NHTSA Recalls Portal within 5 working days of confirming its accuracy:

- Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13 of this part. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA under this section. If your company submits one or more general reimbursement plans, your company shall update each plan every two years, in accordance with § 573.13. Your company's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters (49 CFR 573.6 (c)(8)(i)). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

We have received Cruiser's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement