



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

February 20, 2019

Mr. Andy Jones
Daimler Trucks North America LLC
4747 N. Channel Ave.
Portland, OR 97217

NEF-150MR
18V-913

Subject: Steering and Tie Rod Arm Bolts may be Loose

Dear Mr. Jones:

This letter serves to acknowledge Daimler Trucks North America LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FCCC/MT45/2017-2019
FCCC/MT55G/2017-2019
FCCC/S2G/2017-2019
FCCC/S2RV/2017-2019
FCCC/XBS/2017-2019
FCCC/XCL/2017-2019
FCCC/XCM/2017-2019
FCCC/XCR/2017-2019
FCCC/XCS/2017-2019
FREIGHTLINER/108SD/2017-2019
FREIGHTLINER/114SD/2017-2019
FREIGHTLINER/122SD/2017-2019
FREIGHTLINER/BUSINESS CLASS M2/2017-2019
FREIGHTLINER/CASCADIA/2017-2019
WESTERN STAR/4700/2017-2019
WESTERN STAR/4900/2017-2019
WESTERN STAR/5700/2017-2019

Mfr's Report Date: December 19, 2018

NHTSA Campaign Number: 18V-913

Components:

STEERING
STEERING:LINKAGES:TIE ROD ASSEMBLY
SUSPENSION:FRONT:CONTROL ARM

Potential Number of Units Affected: 501

Problem Description:

Daimler Trucks North America LLC (DTNA) is recalling certain 2017-2019 Freightliner 114SD, 122SD, 108SD, Cascadia and

Business class M2 trucks, Freightliner Custom Chassis XBS, XCL, XCM, MT45, MT55, S2G, S2RV, XCR and XCS custom chassis and Western Star 4700, 4900 and 5700 trucks equipped with Detroit Axle axles. The affected vehicles may have loose steering and tie rod arm bolts.

Consequence:

Loose tie rod arm bolts may lead to separation of the tie rod arm and disconnect of the front wheels of the vehicle, resulting in a loss of vehicle control, increasing the risk of a crash.

Remedy:

DTNA has notified owners, and dealers will inspect the steering arm and tie rod arm bolts for to make sure that they are properly tightened, installing new fasteners as necessary, free of charge. The recall began February 9, 2019. Owners may contact Daimler Trucks at 1-800-547-0712. DTNA's number for this recall is FL-802.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

NHTSA is missing critical, required information for this safety recall. This information must be supplied through the NHTSA Recalls Portal within 5 working days of confirming its accuracy:

- A description of how the products to be recalled differ from similar products that are not included in the recall (49 CFR 573.6 (c) (2)).
- Please provide an estimated percentage of defective vehicles.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

The information in your report suggests that Daimler may have been aware of this issue more than five business days before filing a report with NHTSA. Please be reminded that under Federal law, this agency is to be notified of all safety defect and/or noncompliance decisions within five business days. 49 CFR 573.6

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Kareem Habib
Acting Chief, Recall Management Division
Office of Defects Investigations
Enforcement