



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

February 26, 2019

Mr. Gerrit Hurenkamp
Director of Engineering
Arcimoto Inc
2034 W. 2nd Ave
Eugene, OR 97402

NEF-150JK
18V-945

Subject: Possible Loss of Steering Control

Dear Mr. Hurenkamp:

This letter serves to acknowledge Arcimoto Inc's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

ARCIMOTO/FUV/2017-2018

Mfr's Report Date: December 31, 2018

NHTSA Campaign Number: 18V-945

Components:

STEERING
SUSPENSION:FRONT

Potential Number of Units Affected: 22

Problem Description:

Arcimoto Inc (Arcimoto) is recalling certain 2017-2018 FUV motorcycles. In the affected vehicles, the front suspension and steering system may loosen or wear, possibly resulting in a loss of steering control.

Consequence:

A sudden loss of loss of steering control may increase the risk of a crash.

Remedy:

Arcimoto has notified all affected owners and the motorcycles are within the manufacturer's control. Arcimoto will replace the tie-rods, free of charge. Arcimoto's number for this recall is 7F7-A3N5H-12.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).


It is our understanding that notification to owners began prior to our review of the owner notification letter. Should it become necessary for Arcimoto to do a renotification, the follow-up notification must be submitted to this office for review and it must comply with the requirements of Part 577.5, "Notification pursuant to a manufacturer's decision" and Part 577.10, "Follow-up notification."

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the Arcimoto's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,



Kareem Habib
Acting Chief, Recall Management Division
Office of Defects Investigations
Enforcement