

Recall Quarterly Report**18V-508**

Manufacturer Name : Subaru of America, Inc.
NHTSA Recall No. / MFR Recall No. : 18V-508 /WTU-80
Recall Subject : Missing Spot Welds in B-Pillar Area
Owner Notification Beginning Date : JUL 31, 2018
Owner Notification End Date: AUG 02, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	APR 15, 2019	2019-1	293	293	0	0
2	JAN 21, 2019	2018-4	293	293	0	0
1	OCT 19, 2018	2018-3	293	293	0	0

This Document Last Updated : APR 18, 2019

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.