

Recall Quarterly Report**18V-508**

Manufacturer Name : Subaru of America, Inc.
NHTSA Recall No. / MFR Recall No. : 18V-508 /WTU-80
Recall Subject : Missing Spot Welds in B-Pillar Area
Owner Notification Beginning Date : JUL 31, 2018
Owner Notification End Date: AUG 02, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	OCT 19, 2018	2018-3	293	293	0	0

This Document Last Updated : OCT 26, 2018

Definitions :

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.