

**Recall Quarterly Report****18V-508**

**Manufacturer Name :** Subaru of America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 18V-508 /WTU-80  
**Recall Subject :** Missing Spot Welds in B-Pillar Area  
**Owner Notification Beginning Date :** JUL 31, 2018  
**Owner Notification End Date:** AUG 02, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	JAN 21, 2020	2019-4	293	293	0	0
5	OCT 25, 2019	2019-3	293	293	0	0
4	JUL 05, 2019	2019-2	293	293	0	0
3	APR 15, 2019	2019-1	293	293	0	0
2	JAN 21, 2019	2018-4	293	293	0	0
1	OCT 19, 2018	2018-3	293	293	0	0

This Document Last Updated : JAN 22, 2020

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.