

**Recall Quarterly Report****18V-624****Manufacturer Name :** Forest River, Inc.**NHTSA Recall No. / MFR Recall No. :** 18V-624 /51-0851**Recall Subject :** Missing Bearing Races may cause Hub to Overheat**Owner Notification Beginning Date :** OCT 09, 2018**Owner Notification End Date:** OCT 09, 2018

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
11	JUL 27, 2021	2021-2	935	432	0	0
10	APR 23, 2021	2021-1	935	429	0	0
9	JAN 20, 2021	2020-4	935	428	0	0
8	OCT 20, 2020	2020-3	935	426	0	0
7	JUL 21, 2020	2020-2	935	423	0	0
6	APR 14, 2020	2020-1	935	411	0	0
5	JAN 20, 2020	2019-4	935	411	0	0
4	OCT 31, 2019	2019-3	935	386	0	0
3	OCT 31, 2019	2019-2	935	191	0	0
2	OCT 31, 2019	2019-1	935	117	0	0
1	JAN 16, 2019	2018-4	935	117	0	0

This Document Last Updated : JUL 27, 2021

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.