

Recall Quarterly Report

18V-710

Manufacturer Name : Toyota Motor Engineering & Manufacturing

NHTSA Recall No. / MFR Recall No. : 18V-710 /J0Y

Recall Subject : Insufficiently Tightened Rear Axle Bearing Bolts

Owner Notification Beginning Date : NOV 06, 2018

Owner Notification End Date: NOV 06, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	OCT 22, 2019	2019-3	681	634	12	0
3	JUL 23, 2019	2019-2	681	603	65	0
2	APR 26, 2019	2019-1	681	542	65	0
1	JAN 19, 2019	2018-4	681	424	12	0

This Document Last Updated : OCT 25, 2019

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.