## Part 573 Safety Recall Report

# Manufacturer Name :Dexter Axle CompanySubmission Date :NOV 07, 2018NHTSA Recall No. :18E-100Manufacturer Recall No. :NR

#### Manufacturer Information :

Manufacturer Name :Dexter Axle CompanyAddress :2900 INDUSTRIAL PARKWAY EASTPO BOX 250 ELKHART IN 46516Company phone :574-295-7888

#### **Population :**

Number of potentially involved : 1,677 Estimated percentage with defect : 20 %

云 🔨 🗛 🖈

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

**18E-100** 

#### **Equipment Information :**

Part No. :	Dexter Axle D28H, D35, D44 D28H, D35, D40, D44 2800, 3500, 4000, 4400 lb Cap.
	Trailer Axle
Descriptive Information :	<ul> <li>The population was determined based on reviewing maintenance records and determining that the automatic "greasing" feature on a bearing press was not functioning properly on 9/10/18. The work order for the repair was issued before production started on 9/11/18 and completed and logged on 9/11/18 at ~ 10AM.</li> <li>As a result, some of the inner bearings, in hubs, assembled onto axles built on 9/10/18 may have insufficient gears on one or more of their bearings.</li> <li>The population of axles built on this day that may be affected by this lack of sufficient grease is 1677 axles.</li> </ul>
Production Dates :	SEP 10, 2018 - SEP 10, 2018

#### **Description of Defect :**

Description of the Defect :	Insufficient grease on inner hub bearings
FMVSS 1 :	NR
FMVSS 2 :	NR
1 5	Overheating bearings and hubs and possible bearing failure. Production equipment malfunction.
Identification of Any Warning that can Occur :	Wheel end can run hot and, potentially start to smoke.

The information contained in this report was submitted pursuant to 49 CFR §573

#### **Supplier Identification :**

**Component Manufacturer** 

Name : NR Address : NR NR Country : NR

#### **Chronology**:

Several axles were returned to Dexter Axle with bearing burnouts. An internal investigation followed. It was determined that all the axles returned with bearing burnouts were built in the same plant on the same day. Following up on that information, it was further determined through the examination of maintenance record that automatic bearing lubrication equipment was nonfunctional during one day of production. Many axles have been inspected that were manufactured on the days immediately before and after the day that this piece of equipment was not functioning. The axles made on those days were properly lubricated.

#### **Description of Remedy :**

Description of Remedy Program :	The defect is insufficient grease on the inner bearing. The remedy is to remove the hubs on axles that are part of the population in question. It there is insufficient grease and the bearings are in new condition, the bearings will be repacked and the hubs will be reinstalled. If the bearings appear to show any signs of wear, the hubs and bearings, including cups and cones, will be replaced, with properly packed bearings. If the axle beam shows any damage, it will also be replaced.
	The remedied components: D28H, D35, D40, or D44 model axles; will have hubs with properly lubricated inner bearings.
5	The recall condition was corrected in production 9/11/19 at approximately 10AM through a maintenance action.

#### **Recall Schedule :**

Description of Recall Schedule :	Dexter has begun working with the trailer manufacturers listed in this report. Formal recall letters will be sent by registered mail as soon as
	allowable after the is report has ben filed.
Planned Dealer Notification Date :	NR - NR
Planned Owner Notification Date :	NR - NR

### **18E-100**

Page 3

#### **Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

## Part 573 Safety Recall Report

**18E-100** 

Page 4

N	a 169.
	Gulf Stream
Address :	503 South Oakland Avenue
	Nappanee IN 46550
Country :	
Company Phone :	8002898787
	Heartland
Address :	1140 All Pro Drive
	Elkhart IN 46515
Country :	
Company Phone :	5742663988
Name :	
Address :	903 South Main Street
	Middlebury IN 46540
Country :	US
Company Phone :	5748255861
	Keystone - Dutchmen
Address :	2524 Davis Drive
	Goshen IN 46527
Country :	
Company Phone :	5745373923
	Keystone
Address :	2425 Davis Drive
	Goshen IN 46527
Country :	
Company Phone :	5745373923
	Primetime
Address :	2324 Century Drive
	Goshen IN 46528
Country :	
Company Phone :	5748496904
	Northwood RV
Address :	59998 Smith Loop Road
	LaGrande OR 97850
Country :	
Company Phone :	5419626274

The information contained in this report was submitted pursuant to 49 CFR §573

## Part 573 Safety Recall Report

Name : RV Value Mart Address : 3152 Lebanon Road Manheim PA 17545 Country : US Company Phone : NR

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573

**18E-100**