

Part 573 Safety Recall Report

18V-041

Manufacturer Name : Honda (American Honda Motor Co.)**Submission Date :** JAN 09, 2018**NHTSA Recall No. :** 18V-041**Manufacturer Recall No. :** UOH, GOI**Manufacturer Information :**

Manufacturer Name : Honda (American Honda Motor Co.)

Address : 1919 Torrance Blvd.

Torrance CA 90501

Company phone : 1-888-234-2138

Population :

Number of potentially involved : 24,945

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2009-2009 Acura RL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records and the defect set forth in Takata's notifications to NHTSA (18E-001, 18E-002, and 18E-003). As prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001, the recall population includes certain vehicles originally equipped with a PSPI-L airbag inflator and that are currently registered, ever been registered, or originally sold and/or purchased in specific states or territories.

Similar vehicles are scheduled to be recalled in a later phase as prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.

Production Dates : MAR 18, 2008 - MAR 19, 2009

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2010-2010 Honda Element

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records and the defect set forth in Takata's notifications to NHTSA (18E-001, 18E-002, and 18E-003). As prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001, the recall population includes certain vehicles originally equipped with a PSPI-L airbag inflator and that are currently registered, ever been registered, or originally sold and/or purchased in specific states or territories.

Similar vehicles are scheduled to be recalled in a later phase as prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.

Production Dates : SEP 22, 2009 - OCT 18, 2010

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2010-2010 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records and the defect set forth in Takata's notifications to NHTSA (18E-001, 18E-002, and 18E-003). As prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001, the recall population includes certain vehicles originally equipped with a PSPI-L airbag inflator and that are currently registered, ever been registered, or originally sold and/or purchased in specific states or territories.

Similar vehicles are scheduled to be recalled in a later phase as prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.

Production Dates : AUG 13, 2009 - JUN 09, 2010

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 4 : 2012-2012 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records and the defect set forth in Takata's notifications to NHTSA (18E-001, 18E-002, and 18E-003). As prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001, the recall population includes certain vehicles originally equipped with a PSPI-L airbag inflator and that are currently registered, ever been registered, or originally sold and/or purchased in specific states or territories.

Similar vehicles are scheduled to be recalled in a later phase as prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.

Production Dates : NOV 01, 2011 - SEP 27, 2012

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 5 : 2010-2010 Acura RL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records and the defect set forth in Takata's notifications to NHTSA (18E-001, 18E-002, and 18E-003). As prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001, the recall population includes certain vehicles originally equipped with a PSPI-L airbag inflator and that are currently registered, ever been registered, or originally sold and/or purchased in specific states or territories.

Similar vehicles are scheduled to be recalled in a later phase as prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.

Production Dates : MAY 13, 2009 - SEP 11, 2010

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 6 : 2011-2011 Acura RL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records and the defect set forth in Takata's notifications to NHTSA (18E-001, 18E-002, and 18E-003). As prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001, the recall population includes certain vehicles originally equipped with a PSPI-L airbag inflator and that are currently registered, ever been registered, or originally sold and/or purchased in specific states or territories.

Similar vehicles are scheduled to be recalled in a later phase as prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.

Production Dates : NOV 05, 2010 - APR 28, 2011

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 7 : 2012-2012 Acura RL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records and the defect set forth in Takata's notifications to NHTSA (18E-001, 18E-002, and 18E-003). As prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001, the recall population includes certain vehicles originally equipped with a PSPI-L airbag inflator and that are currently registered, ever been registered, or originally sold and/or purchased in specific states or territories.

Similar vehicles are scheduled to be recalled in a later phase as prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.

Production Dates : NOV 01, 2011 - JUN 07, 2012

VIN Range 1 : Begin : NR End : NR

Not sequential

Vehicle 8 : 2009-2009 Honda Element

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records and the defect set forth in Takata's notifications to NHTSA (18E-001, 18E-002, and 18E-003). As prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001, the recall population includes certain vehicles originally equipped with a

PSPI-L airbag inflator and that are currently registered, ever been registered, or originally sold and/or purchased in specific states or territories.

Similar vehicles are scheduled to be recalled in a later phase as prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.

Production Dates : OCT 24, 2008 - SEP 14, 2009

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 9 : 2011-2011 Honda Element

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records and the defect set forth in Takata's notifications to NHTSA (18E-001, 18E-002, and 18E-003). As prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001, the recall population includes certain vehicles originally equipped with a PSPI-L airbag inflator and that are currently registered, ever been registered, or originally sold and/or purchased in specific states or territories.

Similar vehicles are scheduled to be recalled in a later phase as prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.

Production Dates : OCT 22, 2010 - APR 15, 2011

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 10 : 2009-2009 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records and the defect set forth in Takata's notifications to NHTSA (18E-001, 18E-002, and 18E-003). As prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001, the recall population includes certain vehicles originally equipped with a PSPI-L airbag inflator and that are currently registered, ever been registered, or originally sold and/or purchased in specific states or territories.

Similar vehicles are scheduled to be recalled in a later phase as prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.

Production Dates : JUL 18, 2008 - AUG 11, 2009

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 11 : 2011-2011 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records and the defect

Descriptive Information : set forth in Takata's notifications to NHTSA (18E-001, 18E-002, and 18E-003). As prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001, the recall population includes certain vehicles originally equipped with a PSPI-L airbag inflator and that are currently registered, ever been registered, or originally sold and/or purchased in specific states or territories.

Similar vehicles are scheduled to be recalled in a later phase as prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.

Production Dates : JUN 17, 2010 - OCT 17, 2011

VIN Range 1 : Begin : NR **End :** NR Not sequential

Vehicle 12 : 2013-2013 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records and the defect set forth in Takata's notifications to NHTSA (18E-001, 18E-002, and 18E-003). As prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001, the recall population includes certain vehicles originally equipped with a PSPI-L airbag inflator and that are currently registered, ever been registered, or originally sold and/or purchased in specific states or territories.

Similar vehicles are scheduled to be recalled in a later phase as prescribed in the May 4, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.

Production Dates : SEP 26, 2012 - SEP 04, 2013

VIN Range 1 : Begin : NR **End :** NR Not sequential

Description of Defect :

Description of the Defect : According to the equipment defect notifications (18E-001, 18E-002, and 18E-003) filed by Takata, a defect related to motor vehicle safety may arise in some of the subject non-desiccated PSAN inflators due to propellant degradation occurring after prolonged exposure to high absolute humidity, high temperatures, and high temperature cycling. Activation of a non-desiccated PSAN inflator with degraded propellant may result in an inflator rupture.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : T.K. Holdings, Inc.
Address : 111 Peyerk Court
Romeo MICHIGAN 48065
Country : United States

Chronology :

January 2, 2018

Takata submitted equipment defect notifications (18E-001, 18E-002, and 18E-003) to NHTSA that identified a defect in the subject passenger frontal airbag inflators.

January 9, 2018

Based on the determination by Takata that a defect exists in the subject inflators, as set forth in the equipment defect notification (18E-001, 18E-002, and 18E-003) filed by Takata on January 2, 2018, Honda Motor Co., Ltd., determined a safety defect exists in the affected vehicles and decided to conduct a safety recall.

Description of Remedy :

Description of Remedy Program : The owners of all affected vehicles will be contacted by mail and asked to take their vehicle to a Honda or Acura automobile dealer. The dealer will replace the passenger frontal airbag inflator with a new inflator, free of charge.

How Remedy Component Differs from Recalled Component : Passenger's Frontal Airbag Inflator, Passenger's Frontal Airbag Inflator, Part no.: 77820-SCV-A91ZA, 77820-SJC-A92ZB, 06780-SJA-A80

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Owner notification will begin on or about February 12, 2018
Planned Dealer Notification Date : JAN 10, 2018 - NR
Planned Owner Notification Date : FEB 12, 2018 - NR

* NR - Not Reported