

Part 573 Safety Recall Report

18V-164

Manufacturer Name : Ferrari North America, Inc.

Submission Date : MAR 09, 2018

NHTSA Recall No. : 18V-164

Manufacturer Recall No. : 64



Manufacturer Information :

Manufacturer Name : Ferrari North America, Inc.

Address : 250 Sylvan Avenue

Englewood Cliffs NJ 07632-2500

Company phone : 1800-999-9999

Population :

Number of potentially involved : 40

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2016-2016 Ferrari 488 GTB

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : All vehicles in the production range are included in this campaign.

Production Dates : JUN 03, 2015 - NOV 25, 2015

VIN Range 1 : Begin : ZFF80AMA9G0210118 **End :** ZFF79ALA7G0215384 Not sequential

Vehicle 2 : 2016-2016 Ferrari 488 Spider

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : Only 1 488 Spider is affected by this campaign.

Production Dates : JUN 02, 2015 - JUN 02, 2015

VIN Range 1 : Begin : ZFF80AMA9G0210118 **End :** ZFF80AMA9G0210118 Not sequential

Description of Defect :

Description of the Defect : A software error may cause the software algorithm which calculates the percentage value of wear of the carbo-ceramic brake discs of the vehicle to malfunction.

FMVSS 1 : 135 - Light vehicle brake systems

FMVSS 2 : NR

Description of the Safety Risk : The critical threshold of wear of the brake discs may be reached without the relevant warning lamp and message to the driver. If such condition happens, the worst-case scenario may increase the risk of an accident, due to the brake disc damage.

Description of the Cause : A software error may cause the software algorithm which calculates the percentage value of wear of the carbo-ceramic brake discs of the vehicle to malfunction.

Identification of Any Warning that can Occur : None.

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

Ferrari discovered a discrepancy between estimated and actual wear of the brake discs during scheduled maintenance inspections of the vehicles. After a thorough investigation Ferrari determined that the software did not work properly due to an error.

Description of Remedy :

Description of Remedy Program : Ferrari authorized dealers will update the Instrument Panel Node software, for free, for customers of all affected vehicles. Customers may be eligible to receive reimbursement for the cost associated with this defect provided that the customer sends the original receipt and/or other adequate proof of payment to the company for confirmation of the expenses incurred by the customers.

How Remedy Component Differs from Recalled Component : Not applicable.

Identify How/When Recall Condition was Corrected in Production : The correction in production was made in December 2015.

Recall Schedule :

Description of Recall Schedule : Ferrari will notify dealers and owners within the next month.

Planned Dealer Notification Date : APR 02, 2018 - NR

Planned Owner Notification Date : APR 02, 2018 - NR

* NR - Not Reported