OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name :General Motors LLCSubmission Date :MAY 17, 2018NHTSA Recall No. :18V-267Manufacturer Recall No. :18146

Manufacturer Information :

Manufacturer Name : General Motors LLC

Address : 29427 Louis Chevrolet Road MAIL CODE 480-210-2V WARREN MI 48093 Company phone : 5961733

Vehicle Information :

Vahiala 1.	2009-2014 Che	armalat Silvanad	o UD		
Vehicle Type :		evi olet Sliverau	0 110		
Body Style :					
Power Train :					
Descriptive Information :	affected fire ex identify the GM	tinguishers, GM I vehicles that c	used par ould have	rt number and i e potentially inc	g the make and model of the manufacturing records to cluded those fire extinguishers. her RPO codes in GM's sales
Production Dates :	OCT 13, 2008 -	NOV 06, 2013			
VIN Range 1:	Begin :	NR	End :	NR	□ Not sequential
Vehicle Type : Body Style :					
-	NR Based on the ir affected fire ex identify the GM GM identified a database.	tinguishers, GM I vehicles that c affected vehicles	used par ould have	rt number and i e potentially inc	g the make and model of the manufacturing records to cluded those fire extinguishers. her RPO codes in GM's sales
Descriptive Information : Production Dates :	NR Based on the ir affected fire ex identify the GM GM identified a database. SEP 25, 2008 -	tinguishers, GM I vehicles that c affected vehicles OCT 04, 2013	used par ould have s using th	et number and i e potentially inc e fire extinguis	manufacturing records to cluded those fire extinguishers. her RPO codes in GM's sales
Descriptive Information :	NR Based on the ir affected fire ex identify the GM GM identified a database. SEP 25, 2008 -	tinguishers, GM I vehicles that c affected vehicles	used par ould have	et number and i e potentially inc e fire extinguis	manufacturing records to cluded those fire extinguishers.
Descriptive Information : Production Dates : VIN Range 1 :	NR Based on the ir affected fire ex identify the GM GM identified a database. SEP 25, 2008 -	tinguishers, GM I vehicles that c affected vehicles OCT 04, 2013 NR	used par ould have s using th	et number and i e potentially inc e fire extinguis	manufacturing records to cluded those fire extinguishers. her RPO codes in GM's sales
Descriptive Information : Production Dates : VIN Range 1 : Vehicle 3 : Vehicle Type :	NR Based on the ir affected fire ex identify the GM GM identified a database. SEP 25, 2008 - Begin : 2009-2009 Isu	tinguishers, GM I vehicles that c affected vehicles OCT 04, 2013 NR	used par ould have s using th	et number and i e potentially inc e fire extinguis	manufacturing records to cluded those fire extinguishers. her RPO codes in GM's sales
Descriptive Information : Production Dates : VIN Range 1 : Vehicle 3 :	NR Based on the ir affected fire ex identify the GM GM identified a database. SEP 25, 2008 - Begin : 2009-2009 Isu	tinguishers, GM I vehicles that c affected vehicles OCT 04, 2013 NR	used par ould have s using th	et number and i e potentially inc e fire extinguis	manufacturing records to cluded those fire extinguishers. her RPO codes in GM's sales



18V-267

Population :

Number of potentially involved : 6,154Estimated percentage with defect : 100~%

art 573 Safet	y Reca	all Rep	ort	18V-267	Page
Descriptive Information :	affected fire identify the	extinguishers GM vehicles tl	, GM used part numbers nat could have potential	arding the make and mod and manufacturing reco ly included those fire exti guisher RPO codes in GM	rds to nguishers
Production Dates :					
VIN Range 1:1	segin :	NR	End: NR		sequential
Vehicle 4 : Vehicle Type : Body Style : Power Train :		Chevrolet Exp	ress		
Descriptive Information :	affected fire identify the	extinguishers GM vehicles tl	, GM used part number nat could have potential	arding the make and mod and manufacturing recor ly included those fire exti guisher RPO codes in GM	ds to nguishers
Production Dates :	SEP 09, 200	8 - MAR 23, 20)18		
VIN Range 1: I	Begin :	NR	End: NR	Not s	sequential
Vahiala 5 :	2009-2018	CMC Sayana			
Vehicle Type :	2003-2010	Givic Savalla			
Body Style :					
Power Train :	NP				
Descriptive Information :	Based on the affected fire identify the	extinguishers GM vehicles tl	, GM used part numbers nat could have potential	arding the make and mod and manufacturing reco ly included those fire exti guisher RPO codes in GM	rds to nguishers
Production Dates :	SEP 12, 200	8 - MAR 10, 20)18		
VIN Range 1:1		NR	End: NR	Not s	sequential
Vehicle 6 : Vehicle Type : Body Style : Power Train :		GMC 5000, 60	00, 7000, 8000 Series		
Descriptive Information :	affected fire identify the	extinguishers GM vehicles tl	, GM used part number nat could have potential	arding the make and mod and manufacturing recor- ly included those fire exti guisher RPO codes in GM	ds to nguishers
Production Dates :	AUG 20, 200)8 - JUL 31, 20	09		
i i ouuciion Duics.					

The information contained in this report was submitted pursuant to 49 CFR \$573

18V-267

Page 3

Description of Defect :

Description of the Defect :	Walter Kidde Portable Equipment Inc. ("Kidde") has decided that a defect, which relates to motor vehicle safety, exists in certain Kidde plastic-handle fire extinguishers that GM has determined may have been installed in certain 2009 – 2018 GMC Savana and Chevrolet Express vehicles, 2009 – 2014 GMC Sierra HD and Chevrolet Silverado HD vehicles, 2009 Isuzu F Series, and 2008 GMC 5000, 6000, 7000, and 8000 series vehicles. According to the Defect Information Report filed by Kidde (Recall No. 17E062000), the fire extinguishers may become clogged or require excessive force to activate. According to Kidde, in certain models, the nozzle may detach from the valve assembly with enough force that it could cause injury and render the product inoperable.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	If the fire extinguisher is not operable, it may increase the risk of injury in the event of a fire.
Description of the Cause :	NR
Identification of Any Warning that can Occur :	NR

Supplier Identification :

Componen	t Manufacturer
Name :	Walter Kidde Portable Equipment Inc.
Address :	1016 Corporate Park Dr.
	Mebane NORTH CAROLINA 27302
Country :	United States

Chronology :

See attached - Chronology exceeds 2,000 character limit.

De	escription of Remedy :	
	Description of Remedy Program :	GM will notify owners of affected vehicles to check the serial number on their fire extinguisher and if needed to order a replacement directly from Kidde. GM will refer customers to Kidde for any applicable reimbursement.
	How Remedy Component Differs	Instead of plastic handles and discharge valves, the fire extinguishers will

The information contained in this report was submitted pursuant to 49 CFR §573

from Recalled Component :	contain metal handles and valves. Recalled Component Name: Fire Extinguisher Recalled Component Description: Plastic Straight Handle Fire Extinguisher Recalled Component Part Number: 20880118
	New fire extinguishers containing metal handles and valves are included in all affected vehicles built after 03/23/2018.

Recall Schedule :

Description of Recall Schedule :	General Motors will provide dealer and owner letter notification dates when available.
Planned Dealer Notification Date :	APR 26, 2018 - APR 26, 2018
Planned Owner Notification Date :	NR - NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573