

# Part 573 Safety Recall Report

# 18V-307

**Manufacturer Name :** Newmar Corporation

**Submission Date :** MAY 15, 2018

**NHTSA Recall No. :** 18V-307

**Manufacturer Recall No. :** NR



## Manufacturer Information :

## Population :

**Manufacturer Name :** Newmar Corporation

**Number of potentially involved :** 102

**Address :** 355 North Delaware Street

**Estimated percentage with defect :** 100 %

PO Box 30 Nappanee IN 46550

**Company phone :** 574-773-7791

## Vehicle Information :

**Vehicle 1 :** 2016-2018 Newmar Mountain Aire

**Vehicle Type :** BUSES, MEDIUM & HEAVY VEHICLES

**Body Style :**

**Power Train :** NR

**Descriptive Information :** On certain motorhomes, the DEF (diesel exhaust fluid) tank bracket installed by Spartan Motors, has the potential to make contact with the tag axle tire. This has the possibility to cause damage to the tire and increase the risk of a crash and/or property damage.

**Production Dates :** MAR 17, 2015 - MAY 18, 2018

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

## Description of Defect :

**Description of the Defect :** On certain motorhomes, the DEF (diesel exhaust fluid) tank bracket installed by Spartan Motors, has the potential to make contact with the tag axle tire.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** This has the possibility to cause damage to the tire and increase the risk of a crash and/or property damage.

**Description of the Cause :** The DEF (diesel exhaust fluid) tank bracket installed by Spartan Motors, has the potential to make contact with the tag axle tire.

**Identification of Any Warning that can Occur :** NR

## Supplier Identification :

**Component Manufacturer**

Name : Spartan Motors  
Address : 1541 Reynolds Rd.  
Charlotte MICHIGAN 48813  
Country : United States

**Chronology :**

Newmar was informed of the potential defect and conducted reviewing on April,23 2018. On May 11, 2018, Newmar has made a decision that a safety defect may exist.

**Description of Remedy :**

Description of Remedy Program : This remedy will be done at no cost to the customer. Moving the DEF bracket so it will not make contact with tire.

How Remedy Component Differs from Recalled Component : Pending information from Spartan Motors.

Identify How/When Recall Condition was Corrected in Production : The remedy is being corrected on Spartan Chassis being sent to Newmar.

**Recall Schedule :**

Description of Recall Schedule : On or before 7/10/2018 customer and dealer letters will be mailed out.

Planned Dealer Notification Date : JUL 10, 2018 - JUL 10, 2018

Planned Owner Notification Date : JUL 10, 2018 - JUL 10, 2018

\* NR - Not Reported