

Part 573 Safety Recall Report

18V-547

Manufacturer Name : Winnebago Industries, Inc

Submission Date : APR 08, 2019

NHTSA Recall No. : 18V-547

Manufacturer Recall No. : 153



Manufacturer Information :

Population :

Manufacturer Name : Winnebago Industries, Inc

Number of potentially involved : 1,066

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Estimated percentage with defect : NR

Company phone : 1-641-585-3535

Vehicle Information :

Vehicle 1 : 2018-2019 Winnebago Intent

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All Winnebago Intent Motorhomes are affected. Other products do not have a mirror in this location.

Production Dates : MAY 08, 2017 - AUG 02, 2018

VIN Range 1 : Begin : NR **End :** NR

Not sequential

Description of Defect :

Description of the Defect : The cabinet mirror over the driver seat may not be mechanically secure, and could come loose.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Increased risk of crash if the mirror detaches while the vehicle is in motion.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR
NR
Country : NR

Chronology :

Winnebago Service raised concern of this defect after a mirror came loose and fell into the driver seat. An investigation was started on 08/01/2018 which verified the attachment method was insufficient. On 08/02/2018 a rework campaign was issued to stop shipment of future units and begin rework. On 08/08/2018, a meeting of the Safety Committee was held and the determination was made to conduct a recall campaign.

Description of Remedy :

Description of Remedy Program : Dealer will install 4 screws through the mirror frame, attaching the mirror and frame to the overhead cabinet. The screws will be covered with matching wood plugs. Winnebago authorized service center will submit a Warranty Service Claim to Winnebago.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : Four screws were added for installation of the mirror assembly, fastening to the overhead cabinet.

Recall Schedule :

Description of Recall Schedule : Dealers on or about 1-7-19
Owners were mailed out on 1-21-19

Planned Dealer Notification Date : JAN 07, 2019 - JAN 07, 2019

Planned Owner Notification Date : JAN 21, 2019 - JAN 21, 2019

* NR - Not Reported