

# Part 573 Safety Recall Report

# 18V-547

**Manufacturer Name :** Winnebago Industries, Inc

**Submission Date :** APR 22, 2019

**NHTSA Recall No. :** 18V-547

**Manufacturer Recall No. :** 153



## Manufacturer Information :

**Manufacturer Name :** Winnebago Industries, Inc

**Address :** PO BOX 152  
605 W. Crystal Lake Rd. Forest City IA  
50436

**Company phone :** 1-641-585-3535

## Population :

**Number of potentially involved :** 1,066

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2018-2019 Winnebago Intent

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** All Winnebago Intent Motorhomes are affected. Other products do not have a mirror in this location.

**Production Dates :** MAY 08, 2017 - AUG 02, 2018

**VIN Range 1 : Begin :** NR **End :** NR

Not sequential

## Description of Defect :

**Description of the Defect :** The cabinet mirror over the driver seat may not be mechanically secure, and could come loose.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** Increased risk of crash if the mirror detaches while the vehicle is in motion.

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** NR

## Supplier Identification :

### Component Manufacturer

**Name :** NR

Address : NR  
NR  
Country : NR

**Chronology :**

Winnebago Service raised concern of this defect after a mirror came loose and fell into the driver seat. An investigation was started on 08/01/2018 which verified the attachment method was insufficient. On 08/02/2018 a rework campaign was issued to stop shipment of future units and begin rework. On 08/08/2018, a meeting of the Safety Committee was held and the determination was made to conduct a recall campaign.

**Description of Remedy :**

Description of Remedy Program : Dealer will install 4 screws through the mirror frame, attaching the mirror and frame to the overhead cabinet. The screws will be covered with matching wood plugs. Winnebago authorized service center will submit a Warranty Service Claim to Winnebago.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : Four screws were added for installation of the mirror assembly, fastening to the overhead cabinet.

**Recall Schedule :**

Description of Recall Schedule : Dealers on or about 1-7-19  
Owners were mailed out on 1-21-19

Planned Dealer Notification Date : JAN 07, 2019 - JAN 07, 2019

Planned Owner Notification Date : JAN 21, 2019 - JAN 21, 2019

\* NR - Not Reported