

Part 573 Safety Recall Report**18V-659****Manufacturer Name :** Winnebago Industries, Inc**Submission Date :** OCT 15, 2018**NHTSA Recall No. :** 18V-659**Manufacturer Recall No. :** 154**Manufacturer Information :**

Manufacturer Name : Winnebago Industries, Inc

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 13

Estimated percentage with defect : 69 %

Vehicle Information :

Vehicle 1 : 2019-2019 Winnebago Horizon

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : PTL door latch adjustment

PTL provided 11 door serial numbers that potentially needed to be adjusted. From this information we know the PO numbers and dates these doors were shipped.

Production Dates : JUL 27, 2018 - AUG 24, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Latch rod on entry door improperly adjusted

FMVSS 1 : 206 - Door locks and door retention components

FMVSS 2 : NR

Description of the Safety Risk : If the door opens while moving, it could become a distraction to the vehicle operator and other drivers and or objects may fall out to be come road hazards, which could cause a crash.

Description of the Cause : latch rod adjusted too tight

Identification of Any Warning NR
that can Occur :**Supplier Identification :**

Component Manufacturer

Name : PTL
Address : 3333 John Conley Dr
Lapeer 48446
Country : United States

Chronology :

August 29, 2018 a recall letter 18E-062 was received from PTL and ran a report to locate potentially affected units. August 30 & 31 we then checked our inventory of built units and those in process. Sept , 2018 we checked our Door inventory still in the box and found 2 doors in this recall and sent those back to PTL. Sept 6, 2018 I requested we contacted our dealers with the potentially affected units. We found 5 of the affected doors at our dealerships. Eight units were retailed in this time frame and we will send recall letters out to find the 4 remaining doors.

Description of Remedy :

Description of Remedy Program : Dealers will follow the adjustment procedure provided by PTL
How Remedy Component Differs from Recalled Component : The component is the same (the remedy is an adjustment to the latch)
Identify How/When Recall Condition was Corrected in Production : Affected doors (S/N 29241 and 29249) were removed from inventory and sent back to PTL

Recall Schedule :

Description of Recall Schedule : The dealer letters are scheduled to go out the week of Oct 22, 2018 with the owner letters going out approx. 2 weeks latter.
Planned Dealer Notification Date : OCT 26, 2018 - OCT 26, 2018
Planned Owner Notification Date : OCT 12, 2018 - OCT 12, 2018

* NR - Not Reported