

Part 573 Safety Recall Report

18V-721

Manufacturer Name : Great Dane Trailers

Submission Date : NOV 21, 2018

NHTSA Recall No. : 18V-721

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Great Dane Trailers

Address : 602 E Lathrop Avenue
Savannah GA 31415

Company phone : 912-232-4471

Population :

Number of potentially involved : 64

Estimated percentage with defect : 10 %

Vehicle Information :

Vehicle 1 : 2019-2019 Great Dane Everest CL Reefer

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : A certain number of number of Great Dane Everest CL Reefer trailers built in the Statesboro GA manufacturing facility may have been shipped with missing brake rollers.

Production Dates : JUL 14, 2018 - SEP 28, 2018

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : A certain number of number of Great Dane Everest CL Reefer trailers built in the Statesboro GA manufacturing facility may have been shipped with missing brake rollers.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A trailer missing a one or more brake rollers may have reduced braking ability which could increase stopping distances.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

October 3, 2018 A customer reported finding a trailer missing a brake roller during their inservice inspection
October 7, 2018 The Statesboro manufacturing facility inspected all units remaining at their facility and identified 3 additional affected trailers.
October 8, 2018 Great Dane Warranty discussed with Great Dane engineering the effects of a missing brake roller.
October 11, 2018 A list of potentially affected VINs was completed.

Description of Remedy :

Description of Remedy Program :	Any trailers discovered in the field with one or more missing brake rollers, will have a new roller installed, and the brake shoes and drum inspected for abnormal wear.
How Remedy Component Differs from Recalled Component :	The new brake roller replaces a missing roller
Identify How/When Recall Condition was Corrected in Production :	This condition was corrected in the manufacturing facility on October 7, 2018 when all remaining trailers were inspected and repaired.

Recall Schedule :

Description of Recall Schedule :	All notifications will be sent out by 11/21/2018
Planned Dealer Notification Date :	NOV 21, 2018 - NOV 21, 2018
Planned Owner Notification Date :	NOV 21, 2018 - NOV 21, 2018

* NR - Not Reported