

Part 573 Safety Recall Report

18V-858

Manufacturer Name : McNeilus Truck & Manufacturing, Inc.**Submission Date :** SEP 06, 2019**NHTSA Recall No. :** 18V-858**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :****Manufacturer Name :** McNeilus Truck & Manufacturing, Inc.**Number of potentially involved :** 199**Address :** 524 County Road 34 East**Estimated percentage with defect :** 100 %**P.O. Box** 70 Dodge Center MN 55927**Company phone :** 507-374-6321**Vehicle Information :****Vehicle 1 :** 2016-2018 McNeilus Model: Meridian FEL, Atlantic FEL, XC REL, Bridgmaster Mixer, Standard Mixer, S-Series Mixer**Vehicle Type :** BUSES, MEDIUM & HEAVY VEHICLES**Body Style :** ALL**Power Train :** CNG/LPG**Descriptive Information :** All McNeilus vehicles equipped with Luxfer manufactured One-Turn (OTV) valves.**Production Dates :** DEC 30, 2016 - SEP 28, 2018**VIN Range 1 : Begin :**

NR

End : NR☐ Not sequential**Description of Defect :****Description of the Defect :** A Luxfer valve connected to the CNG tanks within the fuel system may separate under pressure.**FMVSS 1 :** NR**FMVSS 2 :** NR**Description of the Safety Risk :** A Luxfer valve connected to the CNG tanks within the the fuel system may separate under pressure. The separating valve body or handle may strike and injure a person in the vicinity. After separation, the Luxfer valve will leak CNG fuel, which may result in a fire or explosion, resulting in further injuries and property damage.**Description of the Cause :** Valve handle and/or body may separate under pressure.**Identification of Any Warning that can Occur :** No warning provided.**Supplier Identification :**

Component Manufacturer

Name : Luxfer Canada Limited
Address : 4410-46 Avenue SE
Calgary FOREIGN STATES 00 T2B 3N7
Country : Canada

Chronology :

Apr. – Jun, 2018 – McNeilus became aware of valve separations in field.
Jun. 2018 - Supplier informed.
Aug. 2018 – McNeilus aware of additional incidents, supplier informed.
Nov. 2018 - McNeilus aware of additional incidents, supplier informed.
Nov. 2018 – McNeilus decision made to replace OTV valve versus supplier recommendation of utilizing service kit to repair valve stem & knob only.

Description of Remedy :

Description of Remedy Program :	McNeilus will replace defective Luxfer OTV valve with valve from new supplier – OMB. This remedy will be at no cost to the vehicle owner.
How Remedy Component Differs from Recalled Component :	New replacement OMB valve that have different appearance.
Identify How/When Recall Condition was Corrected in Production :	McNeilus will replace in-process vehicles with new valve.

Recall Schedule :

Description of Recall Schedule :	McNeilus does not have dealers for its products.
Planned Dealer Notification Date :	NR - NR
Planned Owner Notification Date :	DEC 21, 2018 - JAN 04, 2019

* NR - Not Reported