

[Next Unread Message](#)[View Message](#)

Sent on	08	07	2018	Expires on	08	26	2018
----------------	----	----	------	-------------------	----	----	------

From	Motorcycle National Field Service
-------------	-----------------------------------

Subject	ACCESSORY SAFETY RECALL: Centerstand, '16-'17 CRF1000L/LD
----------------	---

August 7, 2018

Dear Honda Dealer:

Honda is launching a SAFETY RECALL on the Honda Genuine Accessory Centerstand for 2016-2017 CRF1000L/LD motorcycles for a potential defect that may cause the centerstand to detach from the motorcycle. A detached centerstand increases the risk of a crash and can create a road hazard to other roadway users, or may cause a motorcycle parked on the centerstand to fall over.

NOTE: This is an accessory recall only; units that do not have the recalled centerstand installed are not affected.

Effective immediately, YOU MUST NOT SELL or INSTALL the following Accessory Centerstand:

AFFECTED PART NUMBER

08M70-MJP-G50 – Centerstand ('16-'17 CRF1000L/LD)

DEALER INVENTORY and USED UNITS WITH AFFECTED ACCY. INSTALLED

- Remove the Honda Genuine Accessory Centerstand before selling the unit.

SERVICE BULLETIN

Service Bulletin CRF1000L/LD #1, which includes the affected part number, accessory repair procedure, parts information, as well as warranty claim information, is forthcoming.

PARTS INFORMATION

All dealers with affected accessory inventory must not sell or install the affected parts. Make sure to remove the above part number from any internet parts advertising by your dealership. Dealer parts return information is available on *iN*.

Honda expects that updated parts to repair in-service centerstands will be available the week of August 13, 2018.

CUSTOMER NOTIFICATION

AHM intends to mail customer letters to all owners of 2016-2018 CRF1000L/LD motorcycles as early as possible, subject to State registration information. The letter will inform the customer that their motorcycle may have an installed accessory that is under recall for a safety related defect and advised to have a Honda dealer repair the accessory centerstand.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact AHM TechLine through TechLine Connect on *iN* or contact your District Service Manager.

Sincerely,

American Honda Motor Co., Inc.
Motorcycle Division

Bulletin #: 18-0232