

*** * ADVANCE TECHNICAL INFORMATION NOTICE * ***

DATE: February 9, 2018
TO: Mitsubishi Motors US and Puerto Rico Dealer Principals, Service Managers, and Parts Managers
RE: Sunroof Safety Recall Campaign
ATIN NO. ATIN-18-SR-003-A

AFFECTED VEHICLES: Certain 2007-2010 Outlander, 2008-2010 Lancer, 2009-2010 Lancer Evolution, 2010 Lancer Sportback

PURPOSE

On January 26, 2018, MMNA submitted to the National Highway Traffic Safety Administration (NHTSA) a Defect Information Report regarding certain 2007-2010 Outlander, 2008-2010 Lancer, 2009-2010 Lancer Evolution, and 2010 Lancer Sportback vehicles.

Due to inappropriate polyurethane materials of the outer frame that the sunroof glass is bonded to, the sunroof glass may detach from the sunroof glass assembly. If the sunroof glass detaches while driving, it can become a road hazard, increasing the risk of a crash.

You will be notified again when additional updates become available. In the event you receive any direct customer inquiries regarding this issue, please refer them to the MMNA Customer Relations Hotline at (888) 648-7820. We appreciate your patience while we make the necessary preparations to launch this recall.

IMPORTANT

Affected new or used inventory vehicles must be repaired before the vehicle is sold/delivered. Dealers must check their inventory vehicles' VINs on the Warranty Super Screen to verify whether the vehicle is involved in this recall campaign. It is a violation of Federal law for a dealer to sell/deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied.