Audi AUDI DEALER COMMUNICATION

Revision Available – Safety Recall 69R6 / Driver Frontal Airbag Inflator (Takata)

This notice is for:	✓Dealer Principal✓✓General Manager✓✓Sales Managers✓	Service Manager✓Warranty AdministratorParts Manager✓TechniciansService Advisor✓
Date:	September 27, 2018	
Revision Information:	Updated repair & claiming instructions added for Criteria 05 through 20.	
Repair:	 REVISION AVAILABLE – September 28, 2018 Repair instructions available in ELSA/ServiceNet Check daily campaign open inventory report or OMD for affected vehicles in inventory Repair every affected inventory vehicle <u>before delivery to consumers</u>. 	
Parts Department:	See revised Safety Recall 69R6 campaign circular for detailed parts information.	
Notes:	 Vehicles: Certain 2009-2013 MY Audi vehicles equipped with a Takata driver frontal airbag Schedule owner repairs immediately Owner mailing (Criteria 05 through 20) Anticipated September 2018 	
	IMPORTANT REMINDER: VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS New Vehicles in Dealer Inventory: It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety. Pre-Owned Vehicles in Dealer Inventory: Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.	

-END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Audi Public Relations.

69R6 REV_DLR_LAUNCH