

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS4761  
URGENT - DISTRIBUTE IMMEDIATELY

Date: May 24, 2018

Subject: 18178 - Safety Recall  
Weld Separated on Front Seat Recliner

Models: 2018 Chevrolet Sonic

To: All General Motors Dealers

General Motors is releasing Safety Recall 18178 today. The total number of U.S. vehicles involved is approximately 71. Please see the attached bulletin for details.

**Question and Answer Document (Q&A)**

Attached to this message you will find a document that addresses the ten most likely questions customers may have regarding this Safety Recall. Please use this information as an aid to confidently answer customer concerns.

**Customer Letter Mailing**

The customer letter mailing will begin in the near future.

**Global Warranty Management (GWM)**

The Investigate Vehicle History (IVH) screen in the GWM system will be updated May 24, 2018. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS