



**RECREATIONAL VEHICLE
SAFETY RECALL NOTICE**

Safety Recall: US: 18V-383

CAN: 2018-309

Safety Advisory: 18-322

July 25, 2018

SAFETY ADVISORY 18-322

«Dealer_name»
ATTN: Service Manager
«Street»
«Street_2»
«City», «State» «Zip»
«Country»

Dear «Dealer_name»,

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model 2018-2019 Keystone Cougar Fifth Wheels and Travel Trailers. As a result, Keystone RV is conducting a safety recall.

***Reason for
this recall***

It has been decided that the vehicles in the recall population have an outdoor propane grill installed with clearances that are no longer within the grill manufacturer’s specified tolerances to combustible material. Under certain conditions when using the outside propane grill it is possible for the wooden assembly the grill is installed in to be exposed to elevated temperatures leading to an increased risk of fire. The vehicles included in the recall are:

2018-2019 Keystone Cougar Fifth Wheels and Travel Trailers

Models: 25RES, 26RBS, 26RKS, 27RES, 29BHS, 29RDB, 29RKS, 32BHS, 32DBH, 32RDB, 338RLK, 33MLS, 34TSB, 368MBI, 369BHS, 25BHSWE, 25RESWE, 26RBSWE, 27RESWE, 29BHSWE, 29RDBWE, 30RKSWE, 31BHKWE

Serial Number Ranges:	2018	East	J2503430 - J2513111 JV503523 - JV513269
	2018	West	JC505407 - JC512948
	2019	East	K2500235 - K2501986 KV500092 - KV501824
	2019	West	KC500010 - KC502056

Our records indicate unit(s) sold or in your present lot inventory fall within this range, which will require immediate preventative action. **Important:** If some of the units are still in your inventory, Federal Law requires you to complete the recall service on those units before retail delivery. The unit VIN(s) our records indicate are presently in your inventory or have been sold are as follows:

«VIN1»	«VIN2»	«VIN3»	«VIN4»
«VIN5»	«VIN6»	«VIN7»	«VIN8»
«VIN9»	«VIN10»	«VIN11»	«VIN12»
«VIN13»	«VIN14»	«VIN15»	«VIN16»
«VIN17»	«VIN18»	«VIN19»	«VIN20»
«VIN21»	«VIN22»	«VIN23»	«VIN24»
«VIN25»	«VIN26»	«VIN27»	«VIN28»
«VIN29»	«VIN30»	«VIN31»	«VIN32»
«VIN33»	«VIN34»	«VIN35»	«VIN36»
«VIN37»	«VIN38»	«VIN39»	«VIN40»
«VIN41»	«VIN42»	«VIN43»	«VIN44»
«VIN45»	«VIN46»	«VIN47»	«VIN48»
«VIN49»	«VIN50»	«VIN51»	«VIN52»
«VIN53»	«VIN54»	«VIN55»	«VIN56»
«VIN57»	«VIN58»	«VIN59»	«VIN60»
«VIN61»	«VIN62»	«VIN63»	«VIN64»

«VIN65»	«VIN66»	«VIN67»	«VIN68»
«VIN69»	«VIN70»	«VIN71»	«VIN72»
«VIN73»	«VIN74»	«VIN75»	«VIN76»
«VIN77»	«VIN78»	«VIN79»	«VIN80»
«VIN81»	«VIN82»	«VIN83»	«VIN84»
«VIN85»	«VIN86»	«VIN87»	«VIN88»
«VIN89»	«VIN90»	«VIN91»	«VIN92»
«VIN93»	«VIN94»	«VIN95»	«VIN96»
«VIN97»	«VIN98»	«VIN99»	«VIN100»
«VIN101»	«VIN102»	«VIN103»	«VIN104»
«VIN105»	«VIN106»	«VIN107»	«VIN108»
«VIN109»	«VIN110»	«VIN111»	«VIN112»
«VIN113»	«VIN114»	«VIN115»	«VIN116»
«VIN117»	«VIN118»	«VIN119»	«VIN120»
«VIN121»			

-- Serial numbers with '*' have been retail sold --

Claims for the units which have been serviced must be submitted. Claims submitted will be used by Keystone to record recall service completions and provide dealer payments. Enclosed is a copy of the Safety Advisory #18-322, which details how to remedy the situation and the proper reimbursement procedures.

We apologize for any inconvenience this situation may cause and greatly appreciate your cooperation. Should you have any questions or concerns regarding this correspondence or the enclosed Safety Advisory, please feel free to contact us.

Sincerely,

KEYSTONE RV COMPANY

Rick Deisler
Vice President Service Operations

cc. National Highway Traffic Safety Administration (NHTSA)
cc. Transport Canada