

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager
 Freightliner Dealers – U.S. and Canada
 Western Star and Sterling Dealers – U.S. and Canada
 FCCC Dealers – U.S. and Canada
 Direct Warranty Customers – U.S. and Canada
 Export Distributors

Daimler Truck North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090
 Portland, Oregon 97208-4090

800-547-0712

If you have questions about this Letter, please submit your inquiry on the Web using the [WSC Link on DTNAConnect](#)

REF # ICI23-055

Effective: 12/26/23

Release: 12/26/23

SUBJECT: FL780 – (Sixth) Revised Bulletin

This letter is to inform you that a revised bulletin for Recall FL780 Cascadia ICUC Bulb Check Function is available on the DTNA Portal. Please print and use the revised bulletin for all work under FL780 from this point forward.

REVISION: The Bendix software download procedure has been updated. Changes to both the programming procedure steps and images were also updated.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on the DTNA Portal.

REF # ICI23-055

Date d'entrée en vigueur: 12/26/23

Date de sortie: 12/26/23

OBJET: FL780 – (sixième) Bulletin révisé

La présente lettre vise à vous informer qu'un bulletin révisé sur la fonction de vérification des ampoules ICUC Recall FL780 Cascadia est disponible sur le portail DTNA. Veuillez imprimer et utiliser le bulletin révisé pour tous les travaux effectués dans le cadre du FL780 à partir de maintenant.

RÉVISION: La procédure de téléchargement du logiciel Bendix a été mise à jour. Les modifications apportées aux étapes de la procédure de programmation et aux images ont également été mises à jour.

Si vous avez des questions ou si vous avez besoin de plus amples informations, communiquez avec le service des campagnes de garantie en soumettant une demande par le biais du lien WSC sur le portail DTNA.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.