



IMPORTANT SAFETY RECALL

**AUTOCAR, LLC SAFETY RECALL ACTT-1801
NHTSA RECALL NO. 18V-558**

TO: U.S. and Canadian Distributors, Dealer Principals, Service Managers,
Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act and the Canadian Motor Vehicle Safety Act.

Autocar Industries, LLC has determined that a defect which relates to motor vehicle safety exists in 297 2018-2019 model year Xspotter chassis. These chassis were manufactured between January 19, 2018 and June 27, 2018 with non-sequential serial numbers in the range 226308 through 228430. Accordingly, a recall to address this issue is being initiated effective October 15, 2018.

MODELS Autocar Xspotter MY 2018-2019
AFFECTED:

COMPONENTS Brake Pedal Mounting Plate
AFFECTED:

SAFETY DEFECTS The service brake pedal floor mounting plate may not be welded to specification. If the
AND POTENTIAL brake pedal mounting plate fails, the service brake pedal may become disconnected and
RISKS: non-functional increasing stopping distance and increasing the risk of a crash.

REPAIR The service brake pedal mounting plate will be replaced.
REQUIRED:

REPAIR VIN profiles in the Autocar Warranty System will be updated to show the open recall on
AVAILABLE: October 15, 2018.

REMINDER: It is a violation of Federal law to sell or lease a vehicle covered by this recall notice unless the recall remedy has been completed. Substantial civil penalties apply to violations of this law.

Sincerely,

Autocar Industries, LLC