

From: Broadcast Messaging System
To: [DL-BMS Message Monitors](#)
Subject: BMW Recall 18V-XXX: TurboCord Portable EV Charger
Date: Wednesday, September 26, 2018 12:29:19 PM

Publish Date: September 26, 2018
From: Technical Service
Expiration Date: October 09, 2018

DCSnet Message
Urgent



Subject: BMW Recall 18V-XXX: TurboCord Portable EV Charger

BMW Group is conducting a Voluntary Safety Recall (effective September 26, 2018) on certain BMW TurboCord chargers which can be used with Model Year 2014-2019 BMWi BEV and Rex vehicles and BMW Plug-In Hybrid-Electric vehicles.

Approximately 4,825 vehicles are affected by this recall.

Attachments:

- B61 12 18 (BMW) and Recall Notice
- B61 13 18 (BMW) and Recall Notice
- Q&A
- Faulty Serial Number Check
- Customer Agreement Form
- Step-by-Step Dealer Process Guide

Sincerely,
Technical Service

Attachments:

- [Faulty Serial Numbers Check BMW MINI\[81cc9ce9\].pdf](#)
- [B611318 Recall Notice\[81cc9ce8\].pdf](#)
- [B611318\[81cc9ce7\].pdf](#)
- [B611218 Recall Notice\[81cc9ce6\].pdf](#)
- [B611218\[81cc9ce5\].pdf](#)
- [2018-eVehicles-TurboCordPortableCharger-CustomerAgreement\[81cc9ce4\].pdf](#)
- [2018-eVehicles-BMW-MINI-TurboCordPortableCharger-QA-\(24Sep2018\)\[81cc9ce3\].pdf](#)
- [180925 Dealer Process Rev01\[81cc9c5e\].pdf](#)
- [Faulty Serial Numbers Check BMW MINI\[81cc9ce9\].pdf](#)
- [B611318 Recall Notice\[81cc9ce8\].pdf](#)
- [B611318\[81cc9ce7\].pdf](#)
- [B611218 Recall Notice\[81cc9ce6\].pdf](#)
- [B611218\[81cc9ce5\].pdf](#)
- [2018-eVehicles-TurboCordPortableCharger-CustomerAgreement\[81cc9ce4\].pdf](#)
- [2018-eVehicles-BMW-MINI-TurboCordPortableCharger-QA-\(24Sep2018\)\[81cc9ce3\].pdf](#)
- [180925 Dealer Process Rev01\[81cc9c5e\].pdf](#)

Recipients: BMW Passenger Cars, CC-All
BMW Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel



RECALL 18V-XXX: CHECK BMW TURBOCORD PORTABLE EV CHARGER

MODEL

I01 (i3)	I15 (i8 Roadster)
I12 (i8)	

SITUATION

BMW Group is conducting a Voluntary Safety Recall (effective September 26, 2018) on certain BMW TurboCord chargers which can be used with Model Year 2014-2019 BMWi BEV and Rex vehicles produced from 03/07/2014 up to 08/21 2018.

Approximately 2,232 vehicles are affected by this recall.

Affected vehicles show the campaign as “Open” when checked either in Warranty Vehicle Inquiry, AIR or ISPA Next and identified with the description: **0061850400 B611318 Recall: Check TurboCord Portable EV Charger**. All of the other systems including DAR and the RDR system will show the Stop Sale Sign starting tomorrow. Please utilize the Inventory Campaign Details under ROSS which shows all vehicles that have a Stop Sale in your inventory.

CAUSE

Affected cables were not produced to specifications due to one or more incompatible capacitors on the printed circuit board assembly. An affected cable could overheat and lead to a thermal event or present a shock hazard to the user.

CORRECTION

Inspect the serial number printed on the TurboCord Charger label, either on the charger body 110/240V wall plug, or on the shipping box. Enter the serial number into the “Serial Number Check” attachment, and find out if it is affected by this Recall.

Replace the TurboCord Charger with the improved part, if the serial number is a “bad part” according to the “Serial Number Check” attachment.

In the interim, until the improved TurboCord Charges are available, use the attached “Dealer Process” chart to address vehicles in your inventory.

The defective TurboCord Charger should be returned to the BMW WPRC Parts Return Center, via normal parts return process.

PROCEDURE

--	--

 <p>GRUSB6118-13</p>	<p>BMW TurboCord EV Portable Charger 110/240V</p>
 <p>GRUSB6118-14</p>	<p>Serial number location on the product label placed on the TurboCord Charger shipping box</p>
 <p>GRUSB6118-15</p>	<p>Serial number location on the charger body of the TurboCord Charger</p>

WARRANTY INFORMATION

The campaign Defect Code (00 61 85 04 00) must be used for these Recall repair claim submissions, the corresponding flat rate labor operations will be added as soon as this information is finalized.

Stop-Sale Override during Vehicle RDR: Recall Repair Completed

You will need to have the repair order (RO) number and the RO date to retail (RDR) an affected vehicle once it is repaired as applicable.

Please ensure the claim for this Recall repair is promptly submitted through DCSnet via normal claim entry once the campaign information becomes available as noted above.

NOTE:

As an interim solution to process vehicles affected by Stop-Sale, use the attached procedure "Dealer Process".

ATTACHMENTS

View PDF attachment [180925 Dealer Process Rev01](#).

View PDF attachment [B611318 Recall Notice](#).

View PDF attachment [2018-eVehicles-BMW-MINI-TurboCordPortableCharger-QA-\(24Sep2018\)](#).

View PDF attachment [2018-eVehicles-TurboCordPortableCharger-CustomerAgreement](#).

View PDF attachment [Faulty Serial Numbers Check_BMW_MINI](#).

[Copyright ©2018 BMW of North America, Inc.]

SAFETY RECALL NOTICE

To: All Center Operators, Sales Managers, Service Manager, Parts Manager and Warranty Processor

RE: Recall 18V-XXX: BMW TurboCord Portable EV Charger B61 13 18

BMW Group is conducting a Voluntary Safety Recall (effective September 26, 2018) on certain BMW TurboCord chargers which can be used with Model Year 2014-2019 BMWi BEV and Rex vehicles produced from 03/07/2014 up to 08/21 2018.

Owners will be notified by First Class mail about the Recall and will be instructed to bring their chargers in for a free inspection and, if necessary, replacement when new parts are available from the supplier.


Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Please follow any special instructions that we provide to you for the return or disposition of recall parts.

We appreciate all your assistance with this Recall.

Check Process for Dealer Vehicles



Sales: If you follow the chart and have removed the faulty charger (if applicable), the vehicle can be retailed. Please follow the RDR override instructions under the Warranty section of the bulletin.

For easy find, use CTRL + F, or
click on Edit on toolbar and select Find

Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand
SBE02151809486	BMW	SBE02201809705	BMW	SBE02211809752	BMW	SBE02211809798	BMW
SBE02181809669	BMW	SBE02201809706	BMW	SBE02211809753	BMW	SBE02211809799	BMW
SBE02181809670	BMW	SBE02201809707	BMW	SBE02211809754	BMW	SBE02211809800	BMW
SBE02181809671	BMW	SBE02201809708	BMW	SBE02211809755	BMW	SBE02211809801	BMW
SBE02181809672	BMW	SBE02201809709	BMW	SBE02211809756	BMW	SBE02211809802	BMW
SBE02181809673	BMW	SBE02201809710	BMW	SBE02211809757	BMW	SBE02211809803	BMW
SBE02181809674	BMW	SBE02201809711	BMW	SBE02211809758	BMW	SBE02211809804	BMW
SBE02181809675	BMW	SBE02201809712	BMW	SBE02211809759	BMW	SBE02211809805	BMW
SBE02181809676	BMW	SBE02201809713	BMW	SBE02211809760	BMW	SBE02211809806	BMW
SBE02181809677	BMW	SBE02201809714	BMW	SBE02211809761	BMW	SBE02211809807	BMW
SBE02181809678	BMW	SBE02201809715	BMW	SBE02211809762	BMW	SBE02211809808	BMW
SBE02181809679	BMW	SBE02201809716	BMW	SBE02211809763	BMW	SBE02211809809	BMW
SBE02181809680	BMW	SBE02201809717	BMW	SBE02211809764	BMW	SBE02211809810	BMW
SBE02181809681	BMW	SBE02201809718	BMW	SBE02211809765	BMW	SBE02211809811	BMW
SBE02181809682	BMW	SBE02211809719	BMW	SBE02211809766	BMW	SBE02211809812	BMW
SBE02181809683	BMW	SBE02211809720	BMW	SBE02211809767	BMW	SBE02211809813	BMW
SBE02181809684	BMW	SBE02211809721	BMW	SBE02211809768	BMW	SBE02211809814	BMW
SBE02181809685	BMW	SBE02211809722	BMW	SBE02211809769	BMW	SBE02211809815	BMW
SBE02181809686	BMW	SBE02211809723	BMW	SBE02211809770	BMW	SBE02211809816	BMW
SBE02181809687	BMW	SBE02211809724	BMW	SBE02211809771	BMW	SBE02211809817	BMW
SBE02181809688	BMW	SBE02211809725	BMW	SBE02211809772	BMW	SBE02211809818	BMW
SBE02191802026	MINI	SBE02211809726	BMW	SBE02211809773	BMW	SBE02211809819	BMW
SBE02191802029	MINI	SBE02211809727	BMW	SBE02211809774	BMW	SBE02211809820	BMW
SBE02191802030	MINI	SBE02211809728	BMW	SBE02211809775	BMW	SBE02211809821	BMW
SBE02191802031	MINI	SBE02211809729	BMW	SBE02211809776	BMW	SBE02211809822	BMW
SBE02191802032	MINI	SBE02211809730	BMW	SBE02211809777	BMW	SBE02211809823	BMW
SBE02191802041	MINI	SBE02211809731	BMW	SBE02211809778	BMW	SBE02211809824	BMW
SBE02191802042	MINI	SBE02211809732	BMW	SBE02211809779	BMW	SBE02211809825	BMW
SBE02191802043	MINI	SBE02211809733	BMW	SBE02211809780	BMW	SBE02211809826	BMW
SBE02191802044	MINI	SBE02211809734	BMW	SBE02211809781	BMW	SBE02211809827	BMW
SBE02201809689	BMW	SBE02211809735	BMW	SBE02211809782	BMW	SBE02211809828	BMW
SBE02201809690	BMW	SBE02211809736	BMW	SBE02211809783	BMW	SBE02211809829	BMW
SBE02201809691	BMW	SBE02211809738	BMW	SBE02211809784	BMW	SBE02211809830	BMW
SBE02201809692	BMW	SBE02211809739	BMW	SBE02211809785	BMW	SBE02211809831	BMW
SBE02201809693	BMW	SBE02211809740	BMW	SBE02211809786	BMW	SBE02211809832	BMW
SBE02201809694	BMW	SBE02211809741	BMW	SBE02211809787	BMW	SBE02211809833	BMW
SBE02201809695	BMW	SBE02211809742	BMW	SBE02211809788	BMW	SBE02211809834	BMW
SBE02201809696	BMW	SBE02211809743	BMW	SBE02211809789	BMW	SBE02211809835	BMW
SBE02201809697	BMW	SBE02211809744	BMW	SBE02211809790	BMW	SBE02211809836	BMW
SBE02201809698	BMW	SBE02211809745	BMW	SBE02211809791	BMW	SBE02211809837	BMW
SBE02201809699	BMW	SBE02211809746	BMW	SBE02211809792	BMW	SBE02211809838	BMW
SBE02201809700	BMW	SBE02211809747	BMW	SBE02211809793	BMW	SBE02211809839	BMW
SBE02201809701	BMW	SBE02211809748	BMW	SBE02211809794	BMW	SBE02211809840	BMW
SBE02201809702	BMW	SBE02211809749	BMW	SBE02211809795	BMW	SBE02211809841	BMW
SBE02201809703	BMW	SBE02211809750	BMW	SBE02211809796	BMW	SBE02211809842	BMW
SBE02201809704	BMW	SBE02211809751	BMW	SBE02211809797	BMW	SBE02211809843	BMW

For easy find, use CTRL + F, or
click on Edit on toolbar and select Find

Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand
SBE02211809844	BMW	SBE02211809892	BMW	SBE02211809939	BMW	SBE02211809986	BMW
SBE02211809845	BMW	SBE02211809893	BMW	SBE02211809940	BMW	SBE02211809987	BMW
SBE02211809846	BMW	SBE02211809894	BMW	SBE02211809941	BMW	SBE02211809988	BMW
SBE02211809847	BMW	SBE02211809895	BMW	SBE02211809942	BMW	SBE02211809989	BMW
SBE02211809848	BMW	SBE02211809896	BMW	SBE02211809943	BMW	SBE02211809990	BMW
SBE02211809849	BMW	SBE02211809897	BMW	SBE02211809944	BMW	SBE02211809991	BMW
SBE02211809850	BMW	SBE02211809898	BMW	SBE02211809945	BMW	SBE02211809992	BMW
SBE02211809851	BMW	SBE02211809899	BMW	SBE02211809946	BMW	SBE02211809993	BMW
SBE02211809852	BMW	SBE02211809900	BMW	SBE02211809947	BMW	SBE02211809994	BMW
SBE02211809853	BMW	SBE02211809901	BMW	SBE02211809948	BMW	SBE02211809995	BMW
SBE02211809854	BMW	SBE02211809902	BMW	SBE02211809949	BMW	SBE02211809996	BMW
SBE02211809855	BMW	SBE02211809903	BMW	SBE02211809950	BMW	SBE02211809997	BMW
SBE02211809856	BMW	SBE02211809904	BMW	SBE02211809951	BMW	SBE02211809998	BMW
SBE02211809857	BMW	SBE02211809905	BMW	SBE02211809952	BMW	SBE02211809999	BMW
SBE02211809858	BMW	SBE02211809906	BMW	SBE02211809953	BMW	SBE02211810000	BMW
SBE02211809859	BMW	SBE02211809907	BMW	SBE02211809954	BMW	SBE02211810001	BMW
SBE02211809860	BMW	SBE02211809908	BMW	SBE02211809955	BMW	SBE02211810002	BMW
SBE02211809862	BMW	SBE02211809909	BMW	SBE02211809956	BMW	SBE02211810003	BMW
SBE02211809863	BMW	SBE02211809910	BMW	SBE02211809957	BMW	SBE02211810004	BMW
SBE02211809864	BMW	SBE02211809911	BMW	SBE02211809958	BMW	SBE02211810005	BMW
SBE02211809865	BMW	SBE02211809912	BMW	SBE02211809959	BMW	SBE02211810006	BMW
SBE02211809866	BMW	SBE02211809913	BMW	SBE02211809960	BMW	SBE02211810007	BMW
SBE02211809867	BMW	SBE02211809914	BMW	SBE02211809961	BMW	SBE02211810008	BMW
SBE02211809868	BMW	SBE02211809915	BMW	SBE02211809962	BMW	SBE02211810009	BMW
SBE02211809869	BMW	SBE02211809916	BMW	SBE02211809963	BMW	SBE02211810010	BMW
SBE02211809870	BMW	SBE02211809917	BMW	SBE02211809964	BMW	SBE02211810011	BMW
SBE02211809871	BMW	SBE02211809918	BMW	SBE02211809965	BMW	SBE02211810012	BMW
SBE02211809872	BMW	SBE02211809919	BMW	SBE02211809966	BMW	SBE02211810013	BMW
SBE02211809873	BMW	SBE02211809920	BMW	SBE02211809967	BMW	SBE02211810014	BMW
SBE02211809874	BMW	SBE02211809921	BMW	SBE02211809968	BMW	SBE02211810015	BMW
SBE02211809875	BMW	SBE02211809922	BMW	SBE02211809969	BMW	SBE02211810016	BMW
SBE02211809876	BMW	SBE02211809923	BMW	SBE02211809970	BMW	SBE02211810017	BMW
SBE02211809877	BMW	SBE02211809924	BMW	SBE02211809971	BMW	SBE02211810018	BMW
SBE02211809878	BMW	SBE02211809925	BMW	SBE02211809972	BMW	SBE02231810019	BMW
SBE02211809879	BMW	SBE02211809927	BMW	SBE02211809973	BMW	SBE02231810020	BMW
SBE02211809880	BMW	SBE02211809928	BMW	SBE02211809974	BMW	SBE02231810021	BMW
SBE02211809881	BMW	SBE02211809929	BMW	SBE02211809975	BMW	SBE02231810022	BMW
SBE02211809882	BMW	SBE02211809930	BMW	SBE02211809976	BMW	SBE02231810023	BMW
SBE02211809883	BMW	SBE02211809931	BMW	SBE02211809977	BMW	SBE02231810024	BMW
SBE02211809884	BMW	SBE02211809932	BMW	SBE02211809978	BMW	SBE02231810025	BMW
SBE02211809885	BMW	SBE02211809933	BMW	SBE02211809979	BMW	SBE02231810026	BMW
SBE02211809886	BMW	SBE02211809934	BMW	SBE02211809980	BMW	SBE02231810027	BMW
SBE02211809887	BMW	SBE02211809935	BMW	SBE02211809981	BMW	SBE02231810028	BMW
SBE02211809888	BMW	SBE02211809936	BMW	SBE02211809983	BMW	SBE02231810029	BMW
SBE02211809889	BMW	SBE02211809937	BMW	SBE02211809984	BMW	SBE02231810030	BMW
SBE02211809891	BMW	SBE02211809938	BMW	SBE02211809985	BMW	SBE02231810031	BMW

For easy find, use CTRL + F, or
click on Edit on toolbar and select Find

Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand
SBE02231810032	BMW	SBE02231810078	BMW	SBE02231810125	BMW	SBE02231810171	BMW
SBE02231810033	BMW	SBE02231810079	BMW	SBE02231810126	BMW	SBE02231810172	BMW
SBE02231810034	BMW	SBE02231810080	BMW	SBE02231810127	BMW	SBE02231810173	BMW
SBE02231810035	BMW	SBE02231810081	BMW	SBE02231810128	BMW	SBE02231810174	BMW
SBE02231810036	BMW	SBE02231810082	BMW	SBE02231810129	BMW	SBE02231810175	BMW
SBE02231810037	BMW	SBE02231810083	BMW	SBE02231810130	BMW	SBE02231810176	BMW
SBE02231810038	BMW	SBE02231810084	BMW	SBE02231810131	BMW	SBE02231810177	BMW
SBE02231810039	BMW	SBE02231810085	BMW	SBE02231810132	BMW	SBE02231810178	BMW
SBE02231810040	BMW	SBE02231810086	BMW	SBE02231810133	BMW	SBE02231810179	BMW
SBE02231810041	BMW	SBE02231810087	BMW	SBE02231810134	BMW	SBE02231810180	BMW
SBE02231810042	BMW	SBE02231810088	BMW	SBE02231810135	BMW	SBE02231810181	BMW
SBE02231810043	BMW	SBE02231810089	BMW	SBE02231810136	BMW	SBE02231810182	BMW
SBE02231810044	BMW	SBE02231810090	BMW	SBE02231810137	BMW	SBE02231810183	BMW
SBE02231810045	BMW	SBE02231810091	BMW	SBE02231810138	BMW	SBE02231810184	BMW
SBE02231810046	BMW	SBE02231810092	BMW	SBE02231810139	BMW	SBE02231810185	BMW
SBE02231810047	BMW	SBE02231810093	BMW	SBE02231810140	BMW	SBE02231810186	BMW
SBE02231810048	BMW	SBE02231810094	BMW	SBE02231810141	BMW	SBE02231810187	BMW
SBE02231810049	BMW	SBE02231810095	BMW	SBE02231810142	BMW	SBE02231810188	BMW
SBE02231810050	BMW	SBE02231810097	BMW	SBE02231810143	BMW	SBE02231810189	BMW
SBE02231810051	BMW	SBE02231810098	BMW	SBE02231810144	BMW	SBE02231810190	BMW
SBE02231810052	BMW	SBE02231810099	BMW	SBE02231810145	BMW	SBE02231810191	BMW
SBE02231810053	BMW	SBE02231810100	BMW	SBE02231810146	BMW	SBE02231810192	BMW
SBE02231810054	BMW	SBE02231810101	BMW	SBE02231810147	BMW	SBE02231810193	BMW
SBE02231810055	BMW	SBE02231810102	BMW	SBE02231810148	BMW	SBE02231810195	BMW
SBE02231810056	BMW	SBE02231810103	BMW	SBE02231810149	BMW	SBE02231810196	BMW
SBE02231810057	BMW	SBE02231810104	BMW	SBE02231810150	BMW	SBE02231810197	BMW
SBE02231810058	BMW	SBE02231810105	BMW	SBE02231810151	BMW	SBE02231810198	BMW
SBE02231810059	BMW	SBE02231810106	BMW	SBE02231810152	BMW	SBE02231810199	BMW
SBE02231810060	BMW	SBE02231810107	BMW	SBE02231810153	BMW	SBE02231810200	BMW
SBE02231810061	BMW	SBE02231810108	BMW	SBE02231810154	BMW	SBE02231810201	BMW
SBE02231810062	BMW	SBE02231810109	BMW	SBE02231810155	BMW	SBE02231810202	BMW
SBE02231810063	BMW	SBE02231810110	BMW	SBE02231810156	BMW	SBE02231810203	BMW
SBE02231810064	BMW	SBE02231810111	BMW	SBE02231810157	BMW	SBE02231810204	BMW
SBE02231810065	BMW	SBE02231810112	BMW	SBE02231810158	BMW	SBE02231810205	BMW
SBE02231810066	BMW	SBE02231810113	BMW	SBE02231810159	BMW	SBE02231810206	BMW
SBE02231810067	BMW	SBE02231810114	BMW	SBE02231810160	BMW	SBE02231810207	BMW
SBE02231810068	BMW	SBE02231810115	BMW	SBE02231810161	BMW	SBE02231810208	BMW
SBE02231810069	BMW	SBE02231810116	BMW	SBE02231810162	BMW	SBE02231810209	BMW
SBE02231810070	BMW	SBE02231810117	BMW	SBE02231810163	BMW	SBE02231810210	BMW
SBE02231810071	BMW	SBE02231810118	BMW	SBE02231810164	BMW	SBE02231810211	BMW
SBE02231810072	BMW	SBE02231810119	BMW	SBE02231810165	BMW	SBE02231810212	BMW
SBE02231810073	BMW	SBE02231810120	BMW	SBE02231810166	BMW	SBE02231810213	BMW
SBE02231810074	BMW	SBE02231810121	BMW	SBE02231810167	BMW	SBE02231810215	BMW
SBE02231810075	BMW	SBE02231810122	BMW	SBE02231810168	BMW	SBE02231810216	BMW
SBE02231810076	BMW	SBE02231810123	BMW	SBE02231810169	BMW	SBE02231810217	BMW
SBE02231810077	BMW	SBE02231810124	BMW	SBE02231810170	BMW	SBE02231810218	BMW

For easy find, use CTRL + F, or
click on Edit on toolbar and select Find

Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand
SBE02231810219	BMW	SBE02231810268	BMW	SBE02231810314	BMW	SBE02241810360	BMW
SBE02231810220	BMW	SBE02231810269	BMW	SBE02231810315	BMW	SBE02241810361	BMW
SBE02231810221	BMW	SBE02231810270	BMW	SBE02231810316	BMW	SBE02241810362	BMW
SBE02231810222	BMW	SBE02231810271	BMW	SBE02231810317	BMW	SBE02241810363	BMW
SBE02231810223	BMW	SBE02231810272	BMW	SBE02231810318	BMW	SBE02241810364	BMW
SBE02231810225	BMW	SBE02231810273	BMW	SBE02231810319	BMW	SBE02241810365	BMW
SBE02231810227	BMW	SBE02231810274	BMW	SBE02231810320	BMW	SBE02241810366	BMW
SBE02231810228	BMW	SBE02231810275	BMW	SBE02231810321	BMW	SBE02241810367	BMW
SBE02231810229	BMW	SBE02231810276	BMW	SBE02231810322	BMW	SBE02241810368	BMW
SBE02231810230	BMW	SBE02231810277	BMW	SBE02231810323	BMW	SBE02241810369	BMW
SBE02231810231	BMW	SBE02231810278	BMW	SBE02231810324	BMW	SBE02241810370	BMW
SBE02231810232	BMW	SBE02231810279	BMW	SBE02231810325	BMW	SBE02241810371	BMW
SBE02231810233	BMW	SBE02231810280	BMW	SBE02231810326	BMW	SBE02241810372	BMW
SBE02231810234	BMW	SBE02231810281	BMW	SBE02231810327	BMW	SBE02241810373	BMW
SBE02231810235	BMW	SBE02231810282	BMW	SBE02231810328	BMW	SBE02241810374	BMW
SBE02231810236	BMW	SBE02231810283	BMW	SBE02231810329	BMW	SBE02241810375	BMW
SBE02231810237	BMW	SBE02231810284	BMW	SBE02231810330	BMW	SBE02241810376	BMW
SBE02231810238	BMW	SBE02231810285	BMW	SBE02231810331	BMW	SBE02241810377	BMW
SBE02231810239	BMW	SBE02231810286	BMW	SBE02231810332	BMW	SBE02241810378	BMW
SBE02231810240	BMW	SBE02231810287	BMW	SBE02231810333	BMW	SBE02241810379	BMW
SBE02231810241	BMW	SBE02231810288	BMW	SBE02231810334	BMW	SBE02241810380	BMW
SBE02231810242	BMW	SBE02231810289	BMW	SBE02231810335	BMW	SBE02241810381	BMW
SBE02231810243	BMW	SBE02231810290	BMW	SBE02231810336	BMW	SBE02241810382	BMW
SBE02231810244	BMW	SBE02231810291	BMW	SBE02231810337	BMW	SBE02241810383	BMW
SBE02231810245	BMW	SBE02231810292	BMW	SBE02231810338	BMW	SBE02241810384	BMW
SBE02231810246	BMW	SBE02231810293	BMW	SBE02241810339	BMW	SBE02241810385	BMW
SBE02231810247	BMW	SBE02231810294	BMW	SBE02241810340	BMW	SBE02241810386	BMW
SBE02231810248	BMW	SBE02231810295	BMW	SBE02241810341	BMW	SBE02241810387	BMW
SBE02231810249	BMW	SBE02231810296	BMW	SBE02241810342	BMW	SBE02241810388	BMW
SBE02231810250	BMW	SBE02231810297	BMW	SBE02241810343	BMW	SBE02251810389	BMW
SBE02231810251	BMW	SBE02231810298	BMW	SBE02241810344	BMW	SBE02251810390	BMW
SBE02231810252	BMW	SBE02231810299	BMW	SBE02241810345	BMW	SBE02251810391	BMW
SBE02231810253	BMW	SBE02231810300	BMW	SBE02241810346	BMW	SBE02251810392	BMW
SBE02231810254	BMW	SBE02231810301	BMW	SBE02241810347	BMW	SBE02251810393	BMW
SBE02231810255	BMW	SBE02231810302	BMW	SBE02241810348	BMW	SBE02251810394	BMW
SBE02231810256	BMW	SBE02231810303	BMW	SBE02241810349	BMW	SBE02251810395	BMW
SBE02231810257	BMW	SBE02231810304	BMW	SBE02241810350	BMW	SBE02251810396	BMW
SBE02231810259	BMW	SBE02231810305	BMW	SBE02241810351	BMW	SBE02251810397	BMW
SBE02231810260	BMW	SBE02231810306	BMW	SBE02241810352	BMW	SBE02251810398	BMW
SBE02231810261	BMW	SBE02231810307	BMW	SBE02241810353	BMW	SBE02251810399	BMW
SBE02231810262	BMW	SBE02231810308	BMW	SBE02241810354	BMW	SBE02251810400	BMW
SBE02231810263	BMW	SBE02231810309	BMW	SBE02241810355	BMW	SBE02251810401	BMW
SBE02231810264	BMW	SBE02231810310	BMW	SBE02241810356	BMW	SBE02251810402	BMW
SBE02231810265	BMW	SBE02231810311	BMW	SBE02241810357	BMW	SBE02251810403	BMW
SBE02231810266	BMW	SBE02231810312	BMW	SBE02241810358	BMW	SBE02251810404	BMW
SBE02231810267	BMW	SBE02231810313	BMW	SBE02241810359	BMW	SBE02251810405	BMW

For easy find, use CTRL + F, or
click on Edit on toolbar and select Find

Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand
SBE02251810406	BMW	SBE02251810453	BMW	SBE02251810501	BMW	SBE02251810550	BMW
SBE02251810407	BMW	SBE02251810454	BMW	SBE02251810502	BMW	SBE02251810551	BMW
SBE02251810408	BMW	SBE02251810455	BMW	SBE02251810503	BMW	SBE02251810552	BMW
SBE02251810410	BMW	SBE02251810456	BMW	SBE02251810504	BMW	SBE02251810553	BMW
SBE02251810411	BMW	SBE02251810457	BMW	SBE02251810505	BMW	SBE02251810554	BMW
SBE02251810412	BMW	SBE02251810458	BMW	SBE02251810506	BMW	SBE02251810556	BMW
SBE02251810413	BMW	SBE02251810459	BMW	SBE02251810507	BMW	SBE02251810557	BMW
SBE02251810414	BMW	SBE02251810460	BMW	SBE02251810508	BMW	SBE02251810558	BMW
SBE02251810415	BMW	SBE02251810461	BMW	SBE02251810509	BMW	SBE02251810559	BMW
SBE02251810416	BMW	SBE02251810462	BMW	SBE02251810510	BMW	SBE02251810560	BMW
SBE02251810417	BMW	SBE02251810463	BMW	SBE02251810511	BMW	SBE02251810562	BMW
SBE02251810418	BMW	SBE02251810464	BMW	SBE02251810512	BMW	SBE02251810563	BMW
SBE02251810419	BMW	SBE02251810465	BMW	SBE02251810513	BMW	SBE02251810564	BMW
SBE02251810420	BMW	SBE02251810466	BMW	SBE02251810514	BMW	SBE02251810566	BMW
SBE02251810421	BMW	SBE02251810467	BMW	SBE02251810515	BMW	SBE02251810567	BMW
SBE02251810422	BMW	SBE02251810468	BMW	SBE02251810516	BMW	SBE02251810568	BMW
SBE02251810423	BMW	SBE02251810469	BMW	SBE02251810517	BMW	SBE02251810569	BMW
SBE02251810424	BMW	SBE02251810470	BMW	SBE02251810518	BMW	SBE02251810570	BMW
SBE02251810425	BMW	SBE02251810472	BMW	SBE02251810519	BMW	SBE02251810571	BMW
SBE02251810426	BMW	SBE02251810473	BMW	SBE02251810520	BMW	SBE02251810572	BMW
SBE02251810427	BMW	SBE02251810474	BMW	SBE02251810521	BMW	SBE02251810573	BMW
SBE02251810428	BMW	SBE02251810475	BMW	SBE02251810522	BMW	SBE02251810574	BMW
SBE02251810429	BMW	SBE02251810476	BMW	SBE02251810523	BMW	SBE02251810575	BMW
SBE02251810430	BMW	SBE02251810478	BMW	SBE02251810524	BMW	SBE02251810576	BMW
SBE02251810431	BMW	SBE02251810479	BMW	SBE02251810525	BMW	SBE02251810577	BMW
SBE02251810432	BMW	SBE02251810480	BMW	SBE02251810526	BMW	SBE02251810578	BMW
SBE02251810433	BMW	SBE02251810481	BMW	SBE02251810528	BMW	SBE02251810579	BMW
SBE02251810434	BMW	SBE02251810482	BMW	SBE02251810530	BMW	SBE02251810580	BMW
SBE02251810435	BMW	SBE02251810483	BMW	SBE02251810531	BMW	SBE02251810581	BMW
SBE02251810436	BMW	SBE02251810484	BMW	SBE02251810532	BMW	SBE02251810582	BMW
SBE02251810437	BMW	SBE02251810485	BMW	SBE02251810533	BMW	SBE02251810583	BMW
SBE02251810438	BMW	SBE02251810486	BMW	SBE02251810534	BMW	SBE02251810584	BMW
SBE02251810439	BMW	SBE02251810487	BMW	SBE02251810535	BMW	SBE02251810585	BMW
SBE02251810440	BMW	SBE02251810488	BMW	SBE02251810536	BMW	SBE02251810586	BMW
SBE02251810441	BMW	SBE02251810489	BMW	SBE02251810537	BMW	SBE02251810587	BMW
SBE02251810442	BMW	SBE02251810490	BMW	SBE02251810538	BMW	SBE02251810588	BMW
SBE02251810443	BMW	SBE02251810491	BMW	SBE02251810539	BMW	SBE02251810589	BMW
SBE02251810444	BMW	SBE02251810492	BMW	SBE02251810540	BMW	SBE02251810590	BMW
SBE02251810445	BMW	SBE02251810493	BMW	SBE02251810541	BMW	SBE02251810591	BMW
SBE02251810446	BMW	SBE02251810494	BMW	SBE02251810542	BMW	SBE02251810592	BMW
SBE02251810447	BMW	SBE02251810495	BMW	SBE02251810543	BMW	SBE02251810593	BMW
SBE02251810448	BMW	SBE02251810496	BMW	SBE02251810545	BMW	SBE02251810594	BMW
SBE02251810449	BMW	SBE02251810497	BMW	SBE02251810546	BMW	SBE02251810595	BMW
SBE02251810450	BMW	SBE02251810498	BMW	SBE02251810547	BMW	SBE02251810596	BMW
SBE02251810451	BMW	SBE02251810499	BMW	SBE02251810548	BMW	SBE02251810597	BMW
SBE02251810452	BMW	SBE02251810500	BMW	SBE02251810549	BMW	SBE02251810598	BMW

For easy find, use CTRL + F, or
click on Edit on toolbar and select Find

Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand
SBE02251810599	BMW	SBE02251810645	BMW	SBE02261810691	BMW	SBE02261810739	BMW
SBE02251810600	BMW	SBE02251810646	BMW	SBE02261810692	BMW	SBE02261810740	BMW
SBE02251810601	BMW	SBE02251810647	BMW	SBE02261810693	BMW	SBE02261810741	BMW
SBE02251810602	BMW	SBE02251810648	BMW	SBE02261810694	BMW	SBE02261810742	BMW
SBE02251810603	BMW	SBE02251810649	BMW	SBE02261810695	BMW	SBE02261810744	BMW
SBE02251810604	BMW	SBE02251810650	BMW	SBE02261810696	BMW	SBE02261810745	BMW
SBE02251810605	BMW	SBE02251810651	BMW	SBE02261810697	BMW	SBE02261810746	BMW
SBE02251810606	BMW	SBE02251810652	BMW	SBE02261810698	BMW	SBE02261810747	BMW
SBE02251810607	BMW	SBE02251810653	BMW	SBE02261810699	BMW	SBE02261810748	BMW
SBE02251810608	BMW	SBE02251810654	BMW	SBE02261810700	BMW	SBE02261810750	BMW
SBE02251810609	BMW	SBE02251810655	BMW	SBE02261810701	BMW	SBE02261810751	BMW
SBE02251810610	BMW	SBE02251810656	BMW	SBE02261810702	BMW	SBE02261810752	BMW
SBE02251810611	BMW	SBE02251810657	BMW	SBE02261810703	BMW	SBE02261810753	BMW
SBE02251810612	BMW	SBE02251810658	BMW	SBE02261810704	BMW	SBE02261810754	BMW
SBE02251810613	BMW	SBE02261810659	BMW	SBE02261810705	BMW	SBE02261810755	BMW
SBE02251810614	BMW	SBE02261810660	BMW	SBE02261810706	BMW	SBE02261810756	BMW
SBE02251810615	BMW	SBE02261810661	BMW	SBE02261810707	BMW	SBE02261810757	BMW
SBE02251810616	BMW	SBE02261810662	BMW	SBE02261810708	BMW	SBE02261810759	BMW
SBE02251810617	BMW	SBE02261810663	BMW	SBE02261810709	BMW	SBE02261810760	BMW
SBE02251810618	BMW	SBE02261810664	BMW	SBE02261810710	BMW	SBE02261810761	BMW
SBE02251810619	BMW	SBE02261810665	BMW	SBE02261810711	BMW	SBE02261810762	BMW
SBE02251810620	BMW	SBE02261810666	BMW	SBE02261810712	BMW	SBE02261810763	BMW
SBE02251810621	BMW	SBE02261810667	BMW	SBE02261810713	BMW	SBE02261810764	BMW
SBE02251810622	BMW	SBE02261810668	BMW	SBE02261810714	BMW	SBE02261810765	BMW
SBE02251810623	BMW	SBE02261810669	BMW	SBE02261810715	BMW	SBE02261810766	BMW
SBE02251810624	BMW	SBE02261810670	BMW	SBE02261810716	BMW	SBE02261810767	BMW
SBE02251810625	BMW	SBE02261810671	BMW	SBE02261810717	BMW	SBE02261810768	BMW
SBE02251810626	BMW	SBE02261810672	BMW	SBE02261810718	BMW	SBE02261810769	BMW
SBE02251810627	BMW	SBE02261810673	BMW	SBE02261810719	BMW	SBE02261810770	BMW
SBE02251810628	BMW	SBE02261810674	BMW	SBE02261810720	BMW	SBE02261810771	BMW
SBE02251810629	BMW	SBE02261810675	BMW	SBE02261810721	BMW	SBE02261810772	BMW
SBE02251810630	BMW	SBE02261810676	BMW	SBE02261810722	BMW	SBE02261810773	BMW
SBE02251810631	BMW	SBE02261810677	BMW	SBE02261810723	BMW	SBE02261810774	BMW
SBE02251810632	BMW	SBE02261810678	BMW	SBE02261810724	BMW	SBE02261810775	BMW
SBE02251810633	BMW	SBE02261810679	BMW	SBE02261810725	BMW	SBE02261810776	BMW
SBE02251810634	BMW	SBE02261810680	BMW	SBE02261810726	BMW	SBE02261810777	BMW
SBE02251810635	BMW	SBE02261810681	BMW	SBE02261810727	BMW	SBE02261810778	BMW
SBE02251810636	BMW	SBE02261810682	BMW	SBE02261810728	BMW	SBE02261810779	BMW
SBE02251810637	BMW	SBE02261810683	BMW	SBE02261810729	BMW	SBE02261810780	BMW
SBE02251810638	BMW	SBE02261810684	BMW	SBE02261810730	BMW	SBE02261810781	BMW
SBE02251810639	BMW	SBE02261810685	BMW	SBE02261810731	BMW	SBE02261810782	BMW
SBE02251810640	BMW	SBE02261810686	BMW	SBE02261810732	BMW	SBE02261810783	BMW
SBE02251810641	BMW	SBE02261810687	BMW	SBE02261810733	BMW	SBE02261810784	BMW
SBE02251810642	BMW	SBE02261810688	BMW	SBE02261810734	BMW	SBE02261810785	BMW
SBE02251810643	BMW	SBE02261810689	BMW	SBE02261810737	BMW	SBE02261810786	BMW
SBE02251810644	BMW	SBE02261810690	BMW	SBE02261810738	BMW	SBE02261810787	BMW

For easy find, use CTRL + F, or
click on Edit on toolbar and select Find

Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand
SBE02261810788	BMW	SBE02261810837	BMW	SBE02261810885	BMW	SBE02261810931	BMW
SBE02261810789	BMW	SBE02261810838	BMW	SBE02261810886	BMW	SBE02261810932	BMW
SBE02261810790	BMW	SBE02261810839	BMW	SBE02261810887	BMW	SBE02261810933	BMW
SBE02261810791	BMW	SBE02261810840	BMW	SBE02261810888	BMW	SBE02261810934	BMW
SBE02261810792	BMW	SBE02261810842	BMW	SBE02261810889	BMW	SBE02261810935	BMW
SBE02261810793	BMW	SBE02261810843	BMW	SBE02261810890	BMW	SBE02261810936	BMW
SBE02261810794	BMW	SBE02261810844	BMW	SBE02261810891	BMW	SBE02261810937	BMW
SBE02261810795	BMW	SBE02261810845	BMW	SBE02261810892	BMW	SBE02261810938	BMW
SBE02261810796	BMW	SBE02261810846	BMW	SBE02261810893	BMW	SBE02261810939	BMW
SBE02261810797	BMW	SBE02261810847	BMW	SBE02261810894	BMW	SBE02261810940	BMW
SBE02261810798	BMW	SBE02261810848	BMW	SBE02261810895	BMW	SBE02261810941	BMW
SBE02261810799	BMW	SBE02261810849	BMW	SBE02261810896	BMW	SBE02261810942	BMW
SBE02261810800	BMW	SBE02261810850	BMW	SBE02261810897	BMW	SBE02261810943	BMW
SBE02261810801	BMW	SBE02261810851	BMW	SBE02261810898	BMW	SBE02261810944	BMW
SBE02261810802	BMW	SBE02261810852	BMW	SBE02261810899	BMW	SBE02261810945	BMW
SBE02261810803	BMW	SBE02261810853	BMW	SBE02261810900	BMW	SBE02261810946	BMW
SBE02261810804	BMW	SBE02261810854	BMW	SBE02261810901	BMW	SBE02261810947	BMW
SBE02261810805	BMW	SBE02261810855	BMW	SBE02261810902	BMW	SBE02261810948	BMW
SBE02261810806	BMW	SBE02261810856	BMW	SBE02261810903	BMW	SBE02261810949	BMW
SBE02261810807	BMW	SBE02261810857	BMW	SBE02261810904	BMW	SBE02261810950	BMW
SBE02261810808	BMW	SBE02261810858	BMW	SBE02261810905	BMW	SBE02261810951	BMW
SBE02261810809	BMW	SBE02261810859	BMW	SBE02261810906	BMW	SBE02261810952	BMW
SBE02261810810	BMW	SBE02261810860	BMW	SBE02261810907	BMW	SBE02261810953	BMW
SBE02261810811	BMW	SBE02261810861	BMW	SBE02261810908	BMW	SBE02261810954	BMW
SBE02261810812	BMW	SBE02261810862	BMW	SBE02261810909	BMW	SBE02261810955	BMW
SBE02261810813	BMW	SBE02261810863	BMW	SBE02261810910	BMW	SBE02261810956	BMW
SBE02261810814	BMW	SBE02261810864	BMW	SBE02261810911	BMW	SBE02261810957	BMW
SBE02261810815	BMW	SBE02261810865	BMW	SBE02261810912	BMW	SBE02261810958	BMW
SBE02261810816	BMW	SBE02261810866	BMW	SBE02261810913	BMW	SBE02261810959	BMW
SBE02261810817	BMW	SBE02261810867	BMW	SBE02261810914	BMW	SBE02261810960	BMW
SBE02261810818	BMW	SBE02261810868	BMW	SBE02261810915	BMW	SBE02261810961	BMW
SBE02261810819	BMW	SBE02261810870	BMW	SBE02261810916	BMW	SBE02261810962	BMW
SBE02261810820	BMW	SBE02261810871	BMW	SBE02261810917	BMW	SBE02261810963	BMW
SBE02261810821	BMW	SBE02261810872	BMW	SBE02261810918	BMW	SBE02261810964	BMW
SBE02261810822	BMW	SBE02261810873	BMW	SBE02261810919	BMW	SBE02261810965	BMW
SBE02261810823	BMW	SBE02261810874	BMW	SBE02261810920	BMW	SBE02261810966	BMW
SBE02261810824	BMW	SBE02261810875	BMW	SBE02261810921	BMW	SBE02261810967	BMW
SBE02261810826	BMW	SBE02261810876	BMW	SBE02261810922	BMW	SBE02261810968	BMW
SBE02261810827	BMW	SBE02261810877	BMW	SBE02261810923	BMW	SBE02261810969	BMW
SBE02261810829	BMW	SBE02261810878	BMW	SBE02261810924	BMW	SBE02261810970	BMW
SBE02261810830	BMW	SBE02261810879	BMW	SBE02261810925	BMW	SBE02261810971	BMW
SBE02261810831	BMW	SBE02261810880	BMW	SBE02261810926	BMW	SBE02261810972	BMW
SBE02261810832	BMW	SBE02261810881	BMW	SBE02261810927	BMW	SBE02261810973	BMW
SBE02261810833	BMW	SBE02261810882	BMW	SBE02261810928	BMW	SBE02261810974	BMW
SBE02261810835	BMW	SBE02261810883	BMW	SBE02261810929	BMW	SBE02261810975	BMW
SBE02261810836	BMW	SBE02261810884	BMW	SBE02261810930	BMW	SBE02261810976	BMW

For easy find, use CTRL + F, or
click on Edit on toolbar and select Find

Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand
SBE02261810977	BMW	SBE02301811024	BMW	SBE02301811075	BMW	SBE02301811121	BMW
SBE02261810978	BMW	SBE02301811025	BMW	SBE02301811076	BMW	SBE02301811122	BMW
SBE02301810979	BMW	SBE02301811026	BMW	SBE02301811077	BMW	SBE02301811123	BMW
SBE02301810980	BMW	SBE02301811027	BMW	SBE02301811078	BMW	SBE02301811124	BMW
SBE02301810981	BMW	SBE02301811028	BMW	SBE02301811079	BMW	SBE02301811125	BMW
SBE02301810982	BMW	SBE02301811029	BMW	SBE02301811080	BMW	SBE02301811126	BMW
SBE02301810983	BMW	SBE02301811030	BMW	SBE02301811081	BMW	SBE02301811127	BMW
SBE02301810984	BMW	SBE02301811031	BMW	SBE02301811082	BMW	SBE02301811128	BMW
SBE02301810985	BMW	SBE02301811032	BMW	SBE02301811083	BMW	SBE02301811129	BMW
SBE02301810986	BMW	SBE02301811034	BMW	SBE02301811084	BMW	SBE02301811130	BMW
SBE02301810987	BMW	SBE02301811035	BMW	SBE02301811085	BMW	SBE02301811131	BMW
SBE02301810988	BMW	SBE02301811036	BMW	SBE02301811086	BMW	SBE02301811132	BMW
SBE02301810989	BMW	SBE02301811037	BMW	SBE02301811087	BMW	SBE02301811133	BMW
SBE02301810990	BMW	SBE02301811038	BMW	SBE02301811088	BMW	SBE02301811134	BMW
SBE02301810991	BMW	SBE02301811040	BMW	SBE02301811089	BMW	SBE02301811135	BMW
SBE02301810992	BMW	SBE02301811042	BMW	SBE02301811090	BMW	SBE02301811136	BMW
SBE02301810993	BMW	SBE02301811043	BMW	SBE02301811091	BMW	SBE02301811138	BMW
SBE02301810994	BMW	SBE02301811044	BMW	SBE02301811092	BMW	SBE02301811139	BMW
SBE02301810995	BMW	SBE02301811045	BMW	SBE02301811093	BMW	SBE02301811140	BMW
SBE02301810996	BMW	SBE02301811046	BMW	SBE02301811094	BMW	SBE02301811141	BMW
SBE02301810997	BMW	SBE02301811047	BMW	SBE02301811095	BMW	SBE02301811142	BMW
SBE02301810998	BMW	SBE02301811048	BMW	SBE02301811096	BMW	SBE02301811143	BMW
SBE02301810999	BMW	SBE02301811049	BMW	SBE02301811097	BMW	SBE02301811144	BMW
SBE02301811000	BMW	SBE02301811050	BMW	SBE02301811098	BMW	SBE02301811145	BMW
SBE02301811001	BMW	SBE02301811051	BMW	SBE02301811099	BMW	SBE02301811146	BMW
SBE02301811002	BMW	SBE02301811052	BMW	SBE02301811100	BMW	SBE02301811147	BMW
SBE02301811003	BMW	SBE02301811053	BMW	SBE02301811101	BMW	SBE02301811148	BMW
SBE02301811004	BMW	SBE02301811054	BMW	SBE02301811102	BMW	SBE02301811149	BMW
SBE02301811005	BMW	SBE02301811055	BMW	SBE02301811103	BMW	SBE02301811150	BMW
SBE02301811006	BMW	SBE02301811056	BMW	SBE02301811104	BMW	SBE02301811151	BMW
SBE02301811007	BMW	SBE02301811057	BMW	SBE02301811105	BMW	SBE02301811152	BMW
SBE02301811008	BMW	SBE02301811058	BMW	SBE02301811106	BMW	SBE02301811153	BMW
SBE02301811009	BMW	SBE02301811059	BMW	SBE02301811107	BMW	SBE02301811154	BMW
SBE02301811011	BMW	SBE02301811060	BMW	SBE02301811108	BMW	SBE02301811156	BMW
SBE02301811012	BMW	SBE02301811061	BMW	SBE02301811109	BMW	SBE02301811157	BMW
SBE02301811013	BMW	SBE02301811062	BMW	SBE02301811110	BMW	SBE02301811158	BMW
SBE02301811014	BMW	SBE02301811063	BMW	SBE02301811111	BMW	SBE02301811159	BMW
SBE02301811015	BMW	SBE02301811064	BMW	SBE02301811112	BMW	SBE02301811160	BMW
SBE02301811016	BMW	SBE02301811065	BMW	SBE02301811113	BMW	SBE02301811162	BMW
SBE02301811017	BMW	SBE02301811066	BMW	SBE02301811114	BMW	SBE02301811163	BMW
SBE02301811018	BMW	SBE02301811067	BMW	SBE02301811115	BMW	SBE02301811164	BMW
SBE02301811019	BMW	SBE02301811068	BMW	SBE02301811116	BMW	SBE02301811165	BMW
SBE02301811020	BMW	SBE02301811069	BMW	SBE02301811117	BMW	SBE02301811166	BMW
SBE02301811021	BMW	SBE02301811070	BMW	SBE02301811118	BMW	SBE02301811167	BMW
SBE02301811022	BMW	SBE02301811072	BMW	SBE02301811119	BMW	SBE02301811168	BMW
SBE02301811023	BMW	SBE02301811074	BMW	SBE02301811120	BMW	SBE02301811170	BMW

For easy find, use CTRL + F, or
click on Edit on toolbar and select Find

Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand	Faulty Serial #	Brand
SBE02301811171	BMW	SBE02301811221	BMW	SBE02301811314	BMW	SBE02301811450	BMW
SBE02301811172	BMW	SBE02301811222	BMW	SBE02301811326	BMW	SBE02301811451	BMW
SBE02301811173	BMW	SBE02301811223	BMW	SBE02301811338	BMW	SBE02301811453	BMW
SBE02301811174	BMW	SBE02301811224	BMW	SBE02301811339	BMW	SBE02301811455	BMW
SBE02301811175	BMW	SBE02301811225	BMW	SBE02301811350	BMW	SBE02301811456	BMW
SBE02301811176	BMW	SBE02301811226	BMW	SBE02301811353	BMW	SBE02301811457	BMW
SBE02301811177	BMW	SBE02301811227	BMW	SBE02301811355	BMW	SBE02301811458	BMW
SBE02301811178	BMW	SBE02301811228	BMW	SBE02301811357	BMW	SBE02301811460	BMW
SBE02301811179	BMW	SBE02301811229	BMW	SBE02301811358	BMW	SBE02301811461	BMW
SBE02301811180	BMW	SBE02301811230	BMW	SBE02301811363	BMW	SBE02301811464	BMW
SBE02301811181	BMW	SBE02301811231	BMW	SBE02301811365	BMW	SBE02301811465	BMW
SBE02301811182	BMW	SBE02301811232	BMW	SBE02301811367	BMW	SBE02301811466	BMW
SBE02301811183	BMW	SBE02301811233	BMW	SBE02301811368	BMW	SBE02301811469	BMW
SBE02301811184	BMW	SBE02301811234	BMW	SBE02301811369	BMW	SBE02301811470	BMW
SBE02301811185	BMW	SBE02301811235	BMW	SBE02301811370	BMW	SBE02301811471	BMW
SBE02301811186	BMW	SBE02301811236	BMW	SBE02301811372	BMW	SBE02301811474	BMW
SBE02301811187	BMW	SBE02301811237	BMW	SBE02301811375	BMW	SBE02301811477	BMW
SBE02301811189	BMW	SBE02301811238	BMW	SBE02301811377	BMW	SBE02301811478	BMW
SBE02301811190	BMW	SBE02301811239	BMW	SBE02301811378	BMW	SBE02301811485	BMW
SBE02301811191	BMW	SBE02301811240	BMW	SBE02301811381	BMW	SBE02301811486	BMW
SBE02301811192	BMW	SBE02301811241	BMW	SBE02301811382	BMW	SBE02301811489	BMW
SBE02301811193	BMW	SBE02301811242	BMW	SBE02301811383	BMW	SBE02301811490	BMW
SBE02301811194	BMW	SBE02301811243	BMW	SBE02301811384	BMW	SBE02301811491	BMW
SBE02301811195	BMW	SBE02301811245	BMW	SBE02301811394	BMW	SBE02301811492	BMW
SBE02301811196	BMW	SBE02301811246	BMW	SBE02301811396	BMW	SBE02301811493	BMW
SBE02301811197	BMW	SBE02301811247	BMW	SBE02301811398	BMW	SBE02301811496	BMW
SBE02301811198	BMW	SBE02301811248	BMW	SBE02301811399	BMW	SBE02301811497	BMW
SBE02301811199	BMW	SBE02301811249	BMW	SBE02301811400	BMW	SBE02301811505	BMW
SBE02301811201	BMW	SBE02301811250	BMW	SBE02301811401	BMW	SBE02301811506	BMW
SBE02301811202	BMW	SBE02301811251	BMW	SBE02301811402	BMW	SBE02301811508	BMW
SBE02301811203	BMW	SBE02301811252	BMW	SBE02301811403	BMW	SBE02301811509	BMW
SBE02301811204	BMW	SBE02301811254	BMW	SBE02301811404	BMW	SBE02301811510	BMW
SBE02301811205	BMW	SBE02301811255	BMW	SBE02301811405	BMW	SBE02301811511	BMW
SBE02301811206	BMW	SBE02301811256	BMW	SBE02301811413	BMW	SBE02301811518	BMW
SBE02301811208	BMW	SBE02301811257	BMW	SBE02301811417	BMW	SBE02301811519	BMW
SBE02301811210	BMW	SBE02301811258	BMW	SBE02301811420	BMW	SBE02301811521	BMW
SBE02301811211	BMW	SBE02301811260	BMW	SBE02301811424	BMW	SBE02301811527	BMW
SBE02301811212	BMW	SBE02301811263	BMW	SBE02301811426	BMW	SBE02301811528	BMW
SBE02301811213	BMW	SBE02301811277	BMW	SBE02301811428	BMW	SBE02301811531	BMW
SBE02301811214	BMW	SBE02301811278	BMW	SBE02301811431	BMW	SBE02301811532	BMW
SBE02301811215	BMW	SBE02301811280	BMW	SBE02301811432	BMW	SBE02301811536	BMW
SBE02301811216	BMW	SBE02301811284	BMW	SBE02301811433	BMW	SBE02301811538	BMW
SBE02301811217	BMW	SBE02301811291	BMW	SBE02301811434	BMW	SBE02301811541	BMW
SBE02301811218	BMW	SBE02301811309	BMW	SBE02301811436	BMW	SBE02301811542	BMW
SBE02301811219	BMW	SBE02301811310	BMW	SBE02301811442	BMW	SBE02301811543	BMW
SBE02301811220	BMW	SBE02301811313	BMW	SBE02301811444	BMW	SBE02301811544	BMW

For easy find, use CTRL + F, or
click on Edit on toolbar and select Find

Faulty Serial #	Brand	Faulty Serial #	Brand
SBE02301811545	BMW	SBE02301811610	BMW
SBE02301811546	BMW	SBE02301811636	BMW
SBE02301811548	BMW	SBE02301811638	BMW
SBE02301811549	BMW	SBE02301811641	BMW
SBE02301811550	BMW	SBE02301811647	BMW
SBE02301811551	BMW	SBE02301811649	BMW
SBE02301811552	BMW	SBE02301811651	BMW
SBE02301811553	BMW	SBE02301811653	BMW
SBE02301811555	BMW	SBE02301811656	BMW
SBE02301811559	BMW	SBE02301811661	BMW
SBE02301811560	BMW	SBE02301811662	BMW
SBE02301811561	BMW	SBE02301811672	BMW
SBE02301811562	BMW	SBE02301811675	BMW
SBE02301811563	BMW	SBE02301811676	BMW
SBE02301811564	BMW	SBE02301811677	BMW
SBE02301811565	BMW	SBE02301811679	BMW
SBE02301811566	BMW	SBE02301811680	BMW
SBE02301811567	BMW	SBE02301811683	BMW
SBE02301811568	BMW	SBE02301811684	BMW
SBE02301811569	BMW	SBE02301811688	BMW
SBE02301811570	BMW		
SBE02301811571	BMW		
SBE02301811572	BMW		
SBE02301811573	BMW		
SBE02301811575	BMW		
SBE02301811576	BMW		
SBE02301811577	BMW		
SBE02301811578	BMW		
SBE02301811580	BMW		
SBE02301811581	BMW		
SBE02301811582	BMW		
SBE02301811583	BMW		
SBE02301811584	BMW		
SBE02301811585	BMW		
SBE02301811586	BMW		
SBE02301811587	BMW		
SBE02301811588	BMW		
SBE02301811590	BMW		
SBE02301811591	BMW		
SBE02301811593	BMW		
SBE02301811594	BMW		
SBE02301811600	BMW		
SBE02301811602	BMW		
SBE02301811604	BMW		
SBE02301811605	BMW		
SBE02301811607	BMW		

September 25, 2018

Dear BMW / MINI Owner:


BMW /MINI recently discovered that the TurboCord Portable Charger (“Level 2 charging cable” or “charging cable”) that you purchased was not produced to specifications by the supplier and presents a safety risk. Accordingly, we have provide notice of this issue to the National Highway Traffic Safety Administration (NHTSA). Furthermore, as required, we will need to replace your charging cable with a new one that is not affected by this issue.

Our supplier has not yet been able to produce a sufficient quantity of new cables and, for this reason, we cannot yet provide you with a new charging cable. We sincerely apologize for this temporary inconvenience.

When a sufficient quantity of new parts are available, we will notify you to return to your authorized BMW center / MINI dealer so that we are able to provide you with the new charging cable.

Please be assured that your safety is important to us, and we appreciate your understanding and patience at this time.

Sincerely,



Russ Lucas
VP, Recall Implementation
BMW of North America, LLC

Customer Acknowledgement

BMW / MINI

TurboCord Portable Charger

I _____ am taking delivery of a BMW / MINI Electric or Electric or Hybrid-Electric vehicle VIN: _____ and acknowledge that my BMW center / MINI dealer has removed the TurboCord Portable Charger ("charging cable") from the vehicle prior to the vehicle being delivered to me on this day _____, _____, 2018.

I also understand that BMW / MINI will inform me when a new charging cable is available so that I may return to the BMW center / MINI dealer to receive the new charging cable at no charge.

Customer Signature _____ Date _____

Dealer _____ Dealer Number _____

Dealer Signature _____

BMW center / MINI dealer: Please send a copy to TurboCordSupport@bmwna.com and keep a copy of this form in your customer file.

**Accessory (Port-Installed / Dealer / Online)
TurboCord Portable Charger
18V-xxx / 18E-xxx
Electric / Plug-In Hybrid-Electric Vehicles
*Last Updated 09/24/2018***

Note:

This *****Accessory-Based***** Safety Recall involves the BMW / MINI TurboCord Portable Charger (“charging cable”) produced by supplier Webasto Charging Systems, Inc. It is a “Level 2” charger, i.e., it is capable of connecting the vehicle with a 240Volt electrical outlet for “fast” charging of an Electric / Plug-In Hybrid-Electric vehicle. It is *not* the “Level 1” Occasional Use Cable (OUC) which connects the vehicle to a standard 120Volt electric outlet.

BMW Level 2 Charger



Affected

MINI Level 2 Charger



Affected

Occasional Use Cable (OUC)



Not Affected

The charger is available for BMW / MINI customers as an accessory (port-installed, dealer, online).

Please refer to www.bmwcharging.com / www.minicharging.com for further information.

Owners may have purchased a non-BMW-branded / non-MINI-branded affected cable via other sales channels / third-party providers. The supplier did not provide BMW Group with any identifying information for those charging cables and, therefore, BMW Group cannot support the Safety Recall for those non-branded charging cables.

Q1. Which BMW Group models in the US are potentially affected by this Safety Recall?

Approximately 3,500 BMW / MINI Electric / Plug-In Hybrid-Electric vehicles were processed at Vehicle Distribution Centers (VDC) during the time period (approximately May – Sep) when an affected charging cable may have been installed. Also, approximately 600 affected cables may have been purchased by customers at a BMW center / MINI dealer and/or online.

The following table identifies the specific vehicle models and model years which are potentially affected:

Series	Model	Model Year
F30	330e	2016-2018
G30	530e / 530e xDrive	2018-2019
G12	740Le xDrive	2017-2019
I01	i3 BEV / i3 Rex	2014-2019
I01	i3 Sport BEV / i3 Sport Rex	2018-2019
I12	i8 / i8 Roadster	2014-2019
F15	X5 xDrive40e	2016-2018
F60	MINI Cooper SE Countryman	2018-2019

**Accessory (Port-Installed / Dealer / Online)
TurboCord Portable Charger
18V-xxx / 18E-xxx
Electric / Plug-In Hybrid-Electric Vehicles
*Last Updated 09/24/2018***

Q2. What is the specific issue?

The charging cable was not produced to specifications by the supplier. Specifically, some components on its integrated circuit board are incompatible.

Q3. What can happen as a result of this issue?

The charging cable could present a risk of a thermal event, and it could present a risk of a shock hazard, increasing the risk of injury.

Q4. How did BMW Group become aware of this issue?

BMW Group became aware of this issue through its quality control procedures.

Q5. Why are other BMW Group charging cables not included in this Safety Recall?

Affected Level 2 charging cables have been identified by the supplier by Serial Number. Therefore, the list of affected and unaffected Level 2 charging cables is known. The Level 1 OUC, as noted above, is not affected.

Q6. Can I determine if this issue exists on my Level 2 charging cable?

Your BMW center / MINI dealer will make this determination. Affected Level 2 charging cables have been identified by the supplier by Serial Number. Therefore, please contact an authorized BMW center / MINI dealer. They will inspect and, if necessary, replace an affected cable.

Q7. Can I continue to use my Level 2 charging cable (until a replacement is available)?

No.

When you receive a *letter via First Class mail* from BMW / MINI informing you of this Safety Recall, and asking you to have this Safety Recall performed by an authorized BMW center / MINI dealer, please do so as soon as possible. If you are not the only user of the Level 2 charging cable, please advise all other users of this important information.

i3 BEV / i3 Sport BEV Owners

While we realize that not using the Level 2 charging cable is inconvenient, we are recommending not to use it due to the Safety Recall. Therefore, until a new cable is available, please use the Occasional Use Cable (OUC). We apologize for the temporary inconvenience.

Q8. How will my Level 2 charging cable be repaired?

Affected Level 2 charging cables have been identified by the supplier by Serial Number. Therefore, please contact an authorized BMW center / MINI dealer. They will inspect and, if necessary, replace an affected cable.

**Accessory (Port-Installed / Dealer / Online)
TurboCord Portable Charger
18V-xxx / 18E-xxx
Electric / Plug-In Hybrid-Electric Vehicles
*Last Updated 09/24/2018***

Q9. Is BMW Group aware of any injuries, or fires involving these Level 2 charging cables associated with this Safety Recall?

No.

Q10. How will I be informed of this Safety Recall?

In November, all BMW / MINI Electric / Hybrid-Electric vehicle owners will receive a *letter via First Class mail* asking them to schedule an appointment with their authorized BMW center / MINI dealer to have the Safety Recall performed. When you receive your letter, please have this Safety Recall performed by an authorized BMW center / MINI dealer as soon as possible. You can locate your nearest authorized BMW center at www.bmwusa.com/dealers, or MINI dealer at www.miniusa.com/dealer.

Q11. How long will the repair take?

It shouldn't take long at all. An authorized BMW center / MINI dealer will inspect and, if necessary, replace an affected cable. The inspection and replacement will be performed for free by your authorized BMW center / MINI dealer.

Q12. Do I have to wait for my letter in order to have my charging cable inspected / replaced?

Yes. BMW / MINI are waiting for new charging cables from the supplier.

Q13. I see the "TREAD Act Customer Reimbursement Plan" attached to my letter. Can you explain what that is about? Am I eligible for reimbursement?

If you have already replaced the charging cable at your own expense, you may be eligible for reimbursement of certain expenses that you incurred.