



<p>Safety Recall: 18V-851 2018-686 December 2018</p>

IMPORTANT SAFETY RECALL

Dear Valued Dealer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Jayco has decided that a defect which relates to motor vehicle safety exists in certain Model Year 2019 White Hawk, Jay Flight SLX, and Jay Feather travel trailers.

***Reason for
this recall***

The axle bearings may have an insufficient amount of grease. This may result in premature bearing failure, which can lead to separation of the hub from the axle increasing risk of a crash with personal injury and/or property damage.

***Recall
Remedy***

Remove and inspect bearing grease packing on each Dexter D35 axle per Dexter’s instructions. If inspection reveals axle must be replaced, do so. Contact Dexter at 574-295-7888 for parts required.

All pertinent information regarding this recall is available under the Service and Parts Tab of our Website.

If you require further assistance, please Contact Jayco Customer Service at 800-283-8267.

Our records show the following unit is affected by this recall and is currently part of your inventory.

Unit VIN

***What we
need you to
do***

Federal law requires that all units in your inventory be repaired prior to delivery to a customer. If you have sold a unit recently that you have received a stock recall notice on, please contact the owner immediately to advise of the recall. In addition, please register the unit by submitting the **Warranty Registration Information**.

We certainly regret this inconvenience; however, our Customer’s safety is our most important priority.

Sincerely,
Jayco Towable Division