



864-501-4559
www.TheUSATrailerStore.com

Dear Valued Customer,

This letter is being sent to all customers that have purchased our Heritage motorcycle trailer since August of 2017. It has come to our attention that the welds of the axles may be inadequate. Before further use you must have additional weld added to the points where the axle collet meet the upright.

Attached you will find a diagram showing where the additional weld must be added. We are authorizing up to 100.00 in repair costs. Please submit copies of the receipt for repair and we will make reimbursement. Along with the receipt please include the name of the payee and the address to which the check should be mailed.

If you have trouble finding a welding service that can make the repair, or one that will make the repair for less than 100.00, then please contact us to discuss other options.



We are very sorry about any inconvenience that this may cause, and greatly appreciate your understanding in the matter.

Sincerely,

Troy Shockley, President
TowBlazer, Inc.
d/b/a The USA Trailer Store
1430 Poinsett Hwy
Greenville, SC 29609
864-501-4559
info@theusatrailerstore.com

Towblazer, Inc.
1434 Poinsett Hwy
Greenville SC, 29609

**WELD SAME AREA
ON OPPOSITE SIDE**



WELD ACROSS

