



## SAFETY RECALL

### ACCESSORY CENTERSTAND REPAIR, 2016-2017 CRF1000L/LD

#### AFFECTED UNITS

2016-2017 CRF1000L/LD	All (with affected accessory is installed)
-----------------------	--

#### ACCESSORY SAFETY RECALL

Honda is launching a SAFETY RECALL on the **Honda Genuine Accessory Centerstand** for **2016-2017 CRF1000L/LD** motorcycles for a potential defect that may allow the centerstand to detach from the motorcycle. A detached centerstand increases the risk of a crash and can create a road hazard to other roadway users, or may cause a motorcycle parked on the centerstand to fall over.

**NOTE:** This is an accessory recall only; units that do not have the recalled centerstand installed are not affected.

**Effective immediately, YOU MUST NOT SELL or INSTALL** the affected Accessory Centerstand.

#### AFFECTED PART NUMBER

08M70-MJP-G50 - Centerstand ('16-'17 CRF1000L/LD)

#### DEALER INVENTORY and USED UNITS with AFFECTED ACCY. INSTALLED

- Remove the Honda Genuine Accessory Centerstand before selling the unit.

#### PARTS INFORMATION

All dealers with affected accessory inventory must not sell or install the affected part. Make sure to remove the affected part number from any internet parts advertising by your dealership. Dealer parts return information is available on **IN**.

Honda expects that updated parts to repair in-service centerstands will be available the week of August 13, 2018.

#### REPAIR PROCEDURE

The complete Service Bulletin which includes the accessory repair procedure, parts information, as well as warranty claim information, is forthcoming.

#### DEALER REPAIR RESPONSIBILITY

- Safety Recall repairs must be performed by a qualified technician.
- Installing the remedy parts exactly as shown in Repair Procedure instructions is critical for the recall remedy to be effective. Carefully follow all instructions.
- Service Management should inspect and confirm the repair.
- Dealer submission of a warranty claim affirms this safety recall was properly performed.