



RECALL CAMPAIGN BULLETIN

Classification:	Reference:	Date:
FE18-006	NTB18-088	December 20, 2018

VOLUNTARY SAFETY RECALL CAMPAIGN 2019 ALTIMA; FUEL FEED HOSE RETAINER INSPECTION

CAMPAIGN ID #: PC669
APPLIED VEHICLES: 2019 Altima (L34)
APPLIED ENGINE: PR25DD

**Check Service COMM or Dealer Business Systems (DBS)
National Service History to confirm campaign eligibility.**

INTRODUCTION

Nissan is conducting this voluntary safety recall campaign on certain specific 2019 Altima vehicles to inspect the fuel feed hose retainer. This service will be performed at no charge to the customer for parts or labor.

IDENTIFICATION NUMBER

Nissan has assigned identification number PC669 to this campaign. This number must appear on all communication and documentation of any nature dealing with this campaign.

DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service COMM or Dealer Business Systems (DBS) National Service History for the campaign status on each vehicle falling within the range of this voluntary safety recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. **Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration.** While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

1. Open the hood and secure the hood with the hood prop rod.



Figure 1

2. Locate the fuel feed hose retainer area outlined in Figure 2.
 - The fuel feed hose retainer is red in color.




Figure 2

3. Locate the fuel feed hose retainer shown in Figure 3.




Figure 3

4. Inspect the fuel feed hose retainer using the criteria below.

- If the fuel feed hose retainer is secured as shown in Figure 4, skip to step 7.




Figure 4

- If the fuel feed hose retainer condition is out (not fully locked, similar to Figure 5 and Figure 6), follow the instructions in step 5 on the next page.




Figure 5




Figure 6

5. Insert the fuel hose until fully seated.

6. Push the fuel feed hose retainer until a “click” sound is heard and check that the retainer is securely installed.

- Pull the quick connector by hand and check that is locked.




Figure 7

7. Verify the fuel feed hose is secured in the hose clamp bracket shown in Figure 7.

CLAIMS INFORMATION

Submit a “CM” line claim using the following claims coding:

CAMPAIGN (“CM”) ID	DESCRIPTION	OP CODE	FRT
PC669	Inspect fuel feed hose retainer and lock fuel feed hose retainer, if necessary.	PC6691	0.2 hrs.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
December 20, 2018	NTB18-088	Original bulletin published