

# SRAN557 – LH SWITCHCUBE RECALL / 18V302

Follow-up SMS Campaign – Launched 10<sup>th</sup> December 2019

NHTSA Campaign No: 18V302

Transport Canada Campaign No: 2018249

## SMS MESSAGE SENT TO THE OWNERS

Dear Triumph Owner please visit the below link for important safety recall information.

<http://mpage.info/557>

Reply STOP to cancel msg&data rates may apply

DETAILS ON LANDING PAGE (<http://mpage.info/557>)

# TRIUMPH

**Your Triumph Motorcycle has been identified as having an important open safety recall.**

- DETAILS

Due to incorrectly sealed electrical circuits in the left-hand switch cube, water may contaminate the component and, as a consequence, the turn signal indicator and headlamp control switches may not function correctly.

+ REMEDY

+ WHAT TO DO NEXT

# TRIUMPH

**Your Triumph Motorcycle has been identified as having an important open safety recall.**

+ DETAILS

- REMEDY

The original left hand switch cube will be replaced with a new version. This repair will be performed free of charge.

+ WHAT TO DO NEXT

# TRIUMPH

**Your Triumph Motorcycle has been identified as having an important open safety recall.**

+ DETAILS

+ REMEDY

- WHAT TO DO NEXT

To ensure your maximum safety, we require your co-operation to ensure your motorcycle is modified without delay. Please contact your local or preferred Triumph dealer immediately to book your motorcycle in for the recall work to be carried out free of charge. To find your dealer, please use our Find A Dealer search.