



VIN:

July 2019

URGENT AIRBAG SAFETY RECALL

The replacement airbag module recently installed in your vehicle may have been assembled with an incorrect component.

In the event of a crash, the passenger side airbag may not fully inflate, increasing the risk of injury.

The Lincoln Motor Company cares about the safety of you and your passengers, and we are concerned that you have not yet taken action. Please contact our Airbag Recall Team **IMMEDIATELY** at **866-436-7332** to schedule an appointment for this **FREE** recall repair.

A loaner vehicle can also be provided **FOR FREE.**



IMPORTANT SAFETY RECALL INFORMATION



Issued in Accordance
With Federal Law



VIN:

Julio de 2019

CAMPAÑA DE SEGURIDAD URGENTE DE LA BOLSA DE AIRE

El módulo de la bolsa de aire de reemplazo instalado en su vehículo puede haber sido ensamblado con un componente incorrecto.

En caso de choque, el cojín de la bolsa de aire del lado del pasajero podría no inflarse completamente, **lo cual aumenta el riesgo de sufrir lesiones.**

A Lincoln Motor Company le interesa su seguridad y la de sus pasajeros y nos preocupa que aún no haya tomado ninguna acción. Póngase en contacto **DE INMEDIATO** con nuestro equipo de la campaña de la bolsa de aire al **866-436-7332** a fin de programar una cita para realizar esta campaña, cuya reparación es **GRATUITA.**

Se puede proporcionar un vehículo de prestado también **SIN COSTO.**



CAMPAÑA DE SEGURIDAD DE LA BOLSA DE AIRE

ANUNCIO IMPORTANTE - RETIRO DE SEGURIDAD



Emitido De Acuerdo
Con La Ley Federal



P. O. Box 1904
Dearborn, Michigan 48121-1904

PRESORTED
FIRST CLASS
U.S. POSTAGE
PAID
RKC



771675758417

A/2/000001/0001



JOHN A. SAMPLE
123 SAMPLE ST
SAMPLE CITY, MI 12345-6789

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

