

***** URGENT AIRBAG SAFETY RECALL *****

Safety Recall Notice 18S34 / NHTSA Recall 18V-775

- Ford has learned that **the replacement airbag module recently installed in your vehicle may have been assembled with an incorrect component**. In the event of a crash, the passenger side airbag may not fully inflate, **increasing the risk of injury**.
- Please contact our Airbag Recall Team **immediately** at 866-436-7332 to schedule an appointment for this **FREE** recall repair.
- A loaner vehicle can also be provided **FOR FREE**.

***** CAMPAÑA DE SEGURIDAD URGENTE DE LA BOLSA DE AIRE *****

Aviso de campaña de seguridad 18S34 / Campaña de la NHTSA 18V-775

- Ford se percató de que **el módulo de la bolsa de aire de reemplazo instalado en su vehículo puede haber sido ensamblado con un componente incorrecto**. En caso de choque, el cojín de la bolsa de aire del lado del pasajero podría no inflarse completamente, **lo cual aumenta el riesgo de sufrir lesiones**.
- Póngase en contacto **DE INMEDIATO** con nuestro equipo de la campaña de la bolsa de aire al **866-436-7332** a fin de programar una cita para realizar esta campaña, cuya reparación es **GRATUITA**.
- Se puede proporcionar un vehículo de prestado también **SIN COSTO**.



P. O. Box 1904
Dearborn, Michigan 48121

PRESORTED
FIRST CLASS
U.S. POSTAGE
PAID
RKC



A / 0001 / 000001 / A



JOHN A. SAMPLE
123 SAMPLE ST
SAMPLE CITY, MI 12345-6789

2010 Fusion
Your VIN:

IMPORTANT SAFETY RECALL INFORMATION



Issued in Accordance
With Federal Law



**CAMPAÑA DE SEGURIDAD
DE LA BOLSA DE AIRE**

18S34_SPF