



November, 2019

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2015 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **18S45 - Engine Block Heater Wire Assembly - Water Intrusion/Corrosion**
and Description:

What is the issue? On your vehicle, the engine block heater wire assembly may be susceptible to excess water intrusion or corrosion in the in-line connector. While the vehicle is parked and the block heater is plugged in, an inoperative engine block heater, tripping of household breakers or GFCI equipped outlets, and/or a resistive short may occur. A resistive short may increase the risk of overheated or melted wiring, and/or fire.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: www.Fordowner.com.

Thank you for your attention to this very important matter.

Noviembre de, 2019

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

SegUR nuestros registros, no se realizaron en sur 2015 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **18S45 - Ensamble del cableado del calentador del monoblock**

¿Cuál es el problema? Es posible que el ensamble del cableado del calentador del monoblock del vehículo sea propenso a la entrada de exceso de agua o a la corrosión en el conector en línea. Mientras el vehículo está estacionado y el calentador del monoblock está conectado, es posible que el calentador del monoblock no funcione, que los disyuntores domésticos o las salidas equipadas con GFCI se activen o que se produzca un cortocircuito resistivo. Es posible que un cortocircuito resistivo aumente el riesgo de sobrecalentamiento o derretimiento del cableado o de la producción de un incendio.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: www.Fordowner.com.


Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C


A / 0685 / 000000000000001 / A



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶



▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶