

SERVICE ACTIONS, UPS AND RECALLS UPDATE



- Existing Safety Recall H081 and N138 Fuel Rail leaks
 - Overall c 63% of affected vehicles now repaired
 - Parts remain in restricted supply with supply of all remaining quantities now due to be complete by week 37 (late September).
 - Retailers should continue to escalate open orders as required via the Parts helplines
- UPS 6618 N196 LH Steering Wheel Switch 18MY Range Rover, RR Sport and RR Velar
 - Requires replacement of LH steering wheel switch.
 - Parts are available for immediate supply.
 - UPS campaign will be replaced in August by a Service Action to add all affected sold units.